Lab Wizard 11 User's Guide



Binary Process Solutions

Lab Wizard TM Version 11

Preface

This instruction manual describes the use of Binary Process Solutions Lab Wizard software and is written to cover as many applications as possible. Please do not hesitate to contact Binary Process Solutions or an authorized representative with questions or concerns.

The information in this instruction manual is subject to change without notice as improvements are made, and does not represent any commitment whatsoever on the part of Binary Process Solutions.

Contact Information

To contact Binary Process Solutions technical support: Visit <u>https://lab-wizard.com/contact.html</u> Email to <u>support@lab-wizard.com</u>

Binary Process Solutions License and Warranty

The software, which accompanies this license (the "Software"), is the property of Binary Process Solutions or its licensors. While Binary Process Solutions continues to own the Software, you will have certain rights to use the Software after your acceptance of this license. Except as may be modified by a license addendum which accompanies this license, your rights and obligations with respect to the use of this Software are as follows:

• You may:

(i) use one copy of the Software on a single computer; (ii) make one copy of the Software for archival purposes, or copy the software onto the hard disk of your computer and retain the original for archival purposes.

• You may not:

(i) copy the documentation that accompanies the Software; (ii) transfer, sublicense, rent or lease any portion of the Software; (iii)Reverse engineer, decompile, disassemble, modify, translate, make any attempt to discover the source code of the Software, or create derivative works from the Software; or (iv) use a previous version or copy of the Software after you have installed an upgraded version as a replacement of the prior version. Upon upgrading the Software, all copies of the prior version must be destroyed.

• Limited Warranty:

Binary Process Solutions warrants that the media on which the Software is distributed will be free from defects for a period of ninety (90) days from the date of delivery of the Software to you. Your sole remedy in the event of a breach of this warranty will be that Binary Process Solutions will, at its option, replace any defective media returned to Binary Process Solutions within the warranty period or refund the money you paid for the Software. Binary Process Solutions does not warrant that the Software will meet your requirements or that operation of the Software will be uninterrupted or that the Software will be error-free.

THE ABOVE WARRANTY IS EXCLUSIVE AND IN LIEU OF ALL OTHER WARRANTIES, WHETHER EXPRESS OR IMPLIED, INCLUDING THE IMPLIED WARRANTIES OF MERCHANTADILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT. THIS WARRANTY GIVES YOU SPECIFIC LEGAL RIGHTS. YOU MAY HAVE OTHER RIGHTS, WHICH VARY FROM STATE TO STATE.

• Disclaimer of Damages:

REGARDLESS OF WHETHER ANY REMEDY SET FORTH HEREIN FAILS OF ITS ESSENTIAL PURPOSE, IN NO EVENT WILL BINARY PROCESS SOLUTIONS BE LIABLE TO YOU FOR ANY SPECIAL, CONSEQUENTIAL, INDIRECT OR SIMILAR DAMAGES, INCLUDING ANY LOST PROFITS OR LOST DATA ARISING OUT OF THE USE OR INABILITY TO USE THE SOFTWARE EVEN IF BINARY PROCESS SOLUTIONS HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

SOME STATES DO NOT ALLOW THE LIMITATION OR EXCLUSION OF LIABILITY FOR INCIDENTAL OR CONSEQUENTIAL DAMAGES SO THE ABOVE LIMITATION OR EXCLUSION MAY NOT APPLY TO YOU. IN NO CASE SHALL BINARY PROCESS SOLUTIONS' LIABILITY EXCEED THE PURCHASE PRICE FOR THE SOFTWARE. The disclaimers and limitations set forth above will apply regardless of whether you accept the Software.

• U.S. Government Restricted Rights:

RESTRICTED RIGHTS LEGEND. Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) (1) (ii:) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 or subparagraphs (c) (1) and (2) of the Commercial Computer Software- Restricted Rights clause at 48 CFR 52.227-19, as applicable, Binary Process Solutions, 1250 E Vermont Dr. Gilbert, AZ 85295

• General:

The laws of the State of Arizona will govern this Agreement. This Agreement may only be modified by a license addendum that accompanies this license or by a written document that has been signed by both you and Binary Process Solutions. Should you have any questions concerning this Agreement, or if you desire to contact Binary Process Solutions for any reason, please write to:

Binary Process Solutions 1525 South Higley Rd, Suite # 104 Gilbert, AZ 85296

Table of Contents

INTRODUCTION	1
HARDWARE REQUIREMENTS	4
INSTALLATION INSTRUCTIONS	5
Updating Lab Wizard	5
MAIN SCREEN	6
Operator Log In Changing the Password Operator Log Out Performing Due Analysis.	
SCHEDULED ANALYSIS	
Сомронент Analysis Analysis Entry Edit Add Amount Analysis Menu Options Procedure	
Trend Chart Show Formula Maintenance Add Exclude Data	
Real Time SPC SCHEDULED STATION MAKE-UP TRACKING NUMBER	
MAIN SCREEN MENU	19
SETUP Users and Permissions User Levels Add User Delete User	20 20 20 20 21 21
PROCESS SETUP Menu Options HISTORY	
Process History Out of Spec Causes Pareto Screen Station History	
Station Setup Component History Additional SPC charts SPC Printout	
Cpk Plot Control Chart Editing Corrective Action	

Chart Controls	
Out of Spec Pareto Chart	
Component Setup	35
Preventive Maintenance History	36
Advanced History	
Device Alerts History	.36
Process Undate	37
Product Through_put	
Work Schodulo	
Poporte	20
Evente Statue Depert	
Events Status Report	
Out of Spec Penert	
Cult Of Spec Report	
Dreventive Meintenance Benert	4141 10
Station History Papart	
	43
негр	
Version	
LAB WIZARD SETUP	44
ADDING A PROCESS	
Adding Stations to the Process	45
Adding Components to the Station	46
Component Setup	47
Event Triggering	
Units	
Component Constants	
Process Specification Window	49
Station Make-up Prompt	
Component SPC Setup	50
SPC Rules	50
Action Limits	51
Analysis Procedures	51
Add Instructions	51
Make-up Instructions	
Complex Formulas	51
Setup Menu	
File	52
Edit Pareto Causes	
Global Constants	53
User Mode	
Event Triaaerina Symbols	.54
Proventative Maintenance	55
Croate New PM Tack	
DI Instructione	
Delote DM Item	
Drinting	
1 / Milly	
Auu Tellipiale Sotup Drint Format	۵۵ ۲۰
Setup Fillit Folillat	
Make-up Template	
Out of Spec Template	

Email	
Email Server	
Email Addresses	
Email Recipients	63
Test Email	
PROCESS MODIFICATION	
Modifying a Process	
Deleting a Process	
Modifying a Station	
Deleting a Station	
Modifying a Component	
Deleting a Component	
Duplicate/Rearrange	
Complex Formulas	
Built-in Functions	
Adding Variables	
Creating a New Input	
Concentration formula	71
Add formula	72
Conditional Add	73
Creating Global Constants	
Test Calculation	
BACKUPS	75
REMOTE CONSOLE	76
Hardware Reouirements	
INSTALLATION INSTRUCTIONS	
Updating the Remote Console	
Remote Console Setup	
Remote Console Main Screen	
History drop-down	
Reports drop-down	
Tank Setup	
DASHBOARDS	80
	00
SPC COMPONENT DASHBOARD.	
LIVE STATUS DASHBUARDS	
DASHBOARDS SETUP	
Manage Dashboards Screen	
Component SPC Page Setup	
Component SPC Dashboards Setup	
Live Status Dashboard Setup	

Lab Wizard

Introduction

Lab Wizard has been designed to handle all the lab scheduling, information management, and statistical process control involved in or associated with the wet processing area of a manufacturing environment including preventive maintenance scheduling of the associated equipment.

Upon installation and setup of the program, Lab Wizard will alert the lab tech when any process has a station due for a make-up or analysis. For station make-up, Lab Wizard will print a recipe for make-up of the station. For analysis, the lab tech enters the analysis value of a component and Lab Wizard will calculate the concentration and amount of the addition to bring the component to its target concentration. Lab Wizard will then automatically print an add sheet for the additions that need to be made. If the analysis is out of spec or out of control, Lab Wizard will display a control chart for that component, which will require the lab tech to enter an out of spec cause. If the concentration is beyond the action limits, the appropriate message will be displayed. With the aid of Lab Wizard's trending and SPC charts, the lab tech can easily optimize the interval between analysis by using the dynamic triggers provided for analysis and new make-up scheduling.

These dynamic triggers are separate triggers for each required action. The trigger's interval is maintained based on the three options available. They are time, product, both (triggered by the first due), and none (no triggering). Individual triggers are available for each station's new make-up and for analysis of each component within that station. The station trigger is used for new station make-up. Station make-up may also be triggered by a limit on component concentration value or by the accumulation of adds made since the last make-up. Component triggers are used for analysis. When the triggering is set for time, the time accumulated is the actual time a process is used. The time is process independent and calculated for each process using the "Weekly Work Schedule", accessible through the "Process Update / Work Schedule" menu on the main screen. This is easily accessed and changed to meet the demands of fluctuating work schedules. When a trigger is set for product, the number used is the product output of the process. This number is obtained from the data entered by the operator, by using either the scheduled process pop-up screen, or the "Process Update / Product Throughput" menu on the main screen.

Three symbols are used to help identify the scheduling of events such as analysis or make-ups.

◆ Pre ✓ Event 🗙 Event

These symbols are a diamond, a check mark, or an X and appear in the list boxes on the main screen. A diamond symbol is used for notification of a pending event. The check mark appears in place of the diamond when the event is due. The X mark appears when an event is overdue. An event report is also available for print out. This report will display all events that are overdue, due and almost due, for a user defined, look ahead period.

Enhanced reporting capabilities include:

- 1. Pareto analysis of all processes by the month or months.
- 2. An SPC printout for each component. The SPC printout includes a concentration trending chart that provides a number for any out of spec data, a list displays the out of spec causes for each out of spec data point, a concentration control chart with out of control points numbered, a list of numbered out of control points with the SPC rule violation and corrective action, a moving range chart and a process capability plot.
- 3. Cpk Report for any process displayed down to the component level. Fields displayed are spec limits, control limits, sigma, # of data points, PCI or Cp and Cpk.
- 4. Preventive Maintenance Report displays all PMs with their current status.
- 5. Out of Spec Report for any combination of processes. Displays any component analysis that is out of spec for any time period specified. Options include displaying out of control data and excluded from SPC data.

Run-Time or product throughput triggers?

The most important feature of the Lab Wizard software is its dynamic triggers used to schedule analysis and make-ups by time (run-time) and product throughput. This is the reason the software was created and why it stands alone in the manufacturing community. This is NOT an SPC program. It is a Lab Scheduling and Information Management software that provides fully integrated SPC tools to optimize the interval for analysis and station make-up. The goal of scheduling is to only analyze the components that need analysis and only when necessary while maintaining a consistent interval between analysis. It will be very evident how to attain this goal by using the tools provided.

Most labs use an appointment type of scheduling for analysis and station make-up. Some tanks are analyzed on Monday, Wednesday, and Friday. Some tanks are analyzed on Tuesday and Thursday. Some tanks are analyzed every day or multiple times a day. Unfortunately, several inherent problems occur when using this approach. First, the analysis interval is based on twenty-four hours and has nothing to do with the actual run time of individual processes, unless you run 24 hours seven days a week. Second, the interval between analyses is consistent only when the analysis is done once a week (or weeks), once a day, or multiple times a day. Most manufacturing operations run either five or seven days a week. Five and seven are prime

numbers (can only be divided evenly by themselves or one) and therefore the reason an appointment schedule is limited to only daily (or fractions thereof) and weekly appointments that can achieve consistent analysis intervals. For a five day work week example, if analyses are done Mondays, Wednesdays, and Fridays the interval between analyses will be inconsistent because the run-time interval between Friday and Monday is only one day whereas the other intervals between the weekdays are two days. If analyses are done on Tuesdays and Thursdays the intervals between analyses are still inconsistent due to the three day interval between Thursday and the following Tuesday. Why should you have consistent analysis intervals? Analysis intervals that are not consistent are producing data that is not representative of how the process is actually operating. The SPC and process capability of a process with inconsistent analysis intervals are not a true representation of the process.

Which is better, time (run-time) or product throughput triggers? The clear-cut choice is the product throughput trigger when dealing with chemical processing. The factor that changes concentration the most is drag-in and drag-out of chemistry for most baths. This trigger also accounts for fluctuations of production through a process. The data resulting from analysis triggered by product throughput gives an accurate picture of how the process is really doing, by removing the noise caused by varying amounts of product through a process within an analysis interval. Do you base bath make-ups on time? If you do, start using product throughput for new make-ups and the savings on chemical costs will pay for this software.

The time trigger is used whenever it is not practical to use product throughput for analysis or new make-ups. The time trigger is designed to be much more accurate than time used in an appointment type schedule. Time is only accumulated for a process when the process is scheduled to run. This schedule is setup using the weekly work schedule and can be changed at any time. The interval between analyses are maintained by resetting the trigger each time an analysis is done. The data produced will be more representative of true conditions than that of an appointment schedule. This is due to consistent analysis intervals and the time being the actual process operating time.

A trigger setting of "both" (time and product throughput) should be considered when an analysis that is normally triggered by product throughput exhibits a loss of concentration due to internal chemical reactions. This will trigger an analysis once either setting is reached.

Hardware Requirements

- 1. Personal computer using an Intel Core i5 processor 2 GHz or higher.
- 2. Operating System: 64-bit Windows 10.
- 3. Ram (minimum): 8GB.
- 4. Video adapter capable of 1920x1200 resolution.
- 5. 24" (or larger) monitor with video resolution of 1920x1200.
- 6. An active internet connection is recommended in order to receive software updates.

You can view your computer specifications by clicking the start menu, search for 'This PC', right-click 'This PC' and select 'properties'. You will see a screen like the following:

View basic information	about your computer
Windows edition	
Windows 10 Pro	
© 2018 Microsoft Corporat	tion. All rights reserved.
System	
Processor:	Intel(R) Core(TM) i7-6500U CPU @ 2.50GHz 2.59 GHz
Installed memory (RAM):	8.00 GB
System type:	64-bit Operating System, x64-based processor
Pen and Touch:	No Pen or Touch Input is available for this Display

NOTE: To keep the process data as accurate as possible, it is strongly recommended that the computer be dedicated to Lab Wizard and is running whenever any process is running.

To set the video resolution:

- 1. Right click on the desktop.
- 2. Select 'Display Settings'
- 3. Scroll down to 'resolution' and select 1920x1200 from the drop-down menu.

Installation Instructions

If you are upgrading an existing Lab Wizard, you must rename or backup the LabWizard directory BEFORE installing this version. The new windows installer will delete the existing version.

- 1. If you are upgrading from a previous version please contact the Lab Wizard team to get a quote for data migration as the new database used is MySQL which is not compatible with databases used in previous versions.
- 2. Ensure the Operating system has all updates installed and the system has been restarted.
- 3. Download the latest version of the Lab Wizard software using the link in your email.
- 4. Once the download is complete right-click the LabWizard.zip file and select 'Extract' All' then click the 'Extract' button.
- 5. Close out all active programs and any open windows.
- 6. Double-click the setup.exe file and follow the prompts.
- 7. Proceed through the installation using all of the default options, once the entire installation is complete you will be prompted to restart, DO NOT exit before this.
- 8. You must have administrator privileges in order to install the software, when you are prompted enter the administrative credentials.
- 9. This software requires a license file, which is generated by the Lab-Wizard team. If you are having trouble starting the software due to a missing LW.ini file please contact support for assistance.

After completing the above steps, start the program. Click on the current user to log in. The default admin password is <u>admin</u>.

Updating Lab Wizard

Any time Lab Wizard is launched a small window will appear asking to check for updates. Selecting 'No' will simply launch Lab Wizard. Selecting 'Yes' will check for any updates, if an update is found then it will be automatically downloaded and installed before launching Lab Wizard.

Yes	No
Current running ve	rsion is 11.4.47
OK	

Check for updates?

To check the current version of Lab Wizard, Select 'Version' under the 'Help' menu on the main screen.

Main Screen



The main screen displays the current status of all processes by placing a symbol next to the processes that need attention. The list box labeled "Process" shows all the processes. The "Stations" list box shows all the stations of the process that are highlighted in the "Process" list box. The "Components" list box shows all the components of the station that are highlighted in the "Stations" list box. When an event is almost due (user defined), a diamond symbol appears in next to the item. A check mark symbol appears next to any item when the event is due and an "X" symbol indicates an event is overdue. A red border around these three list boxes will appear when an action is overdue. The event becomes overdue when it has been due for a percentage of the trigger value (user defined).

Select the "Events Due Now" option to see the events due for the highlighted station in the "Stations" list box and select the "Upcoming Events" option to display events that are not currently due, but are scheduled for that station at a later date. The "Tracking #" indicator displays the last number used for an add or make-up sheet. The "Current User" indicator displays the name of the operator that is logged on.

The bottom left text box lists all add and make-up sheets that have been issued and not closed out. The check mark to the left will become an X (overdue) if the action is not completed before a user defined percentage of the analysis trigger value. A red border around this text box indicates that one of the entries is overdue.

To close out a listed action, click the action and the following screen appears:

Binary Process Solutions Gilbert, Arizona Add Sheet	
ADD SLIP Tracking #000001	
Date: 9/12/2021	
Time: 2:56 PM	
Process: Lane 3 - Plater	
Station: Copper Strike	
Station #: 56-57	
Safety Equipment: Wear Safety glasses, gloves and apron.	
PLEASE MAKE THE FOLLOWING ADDITIONS:	
Copper Sulfate> 168.00 pounds	
Sulfuric Acid> 5.47 gallons	
Chloride (HCL)> 30.96 mls	
Issued By: admin Initials:	
Adds Made By: Date: Time:	
······································	
Completed By	
Sarah Print Action Completed	Cancel

Press the "Action Completed" button to close out the issued sheet. Another copy of the sheet can be printed from this window with the "Print" button. Users with access level 4 or 5 can mark the issued sheet as completed by a different user by the "Completed by" drop-down list.

The bottom right text box lists any preventive maintenance items that are due. The check mark to the left will become an X (overdue) if the preventive maintenance is not completed by the number of days specified in the preventive maintenance setup for the displayed item. To close out the line item, click on the line and the following screen appears:

Weekly Activator 1000 Addition	
PM Instructions	
Follow all safety guidelines in the MSDS and add the calculated amount of Activator 1000.	^
Completed by: admin Print Completed Cancel	

Click on "PM Completed" button to mark the PM as complete. A print option is also available if printing the PM instructions are desired. Users with access level 4 or 5 can change which user completed the PM via the "Completed by" drop-down list.

Date and time is displayed in the upper right portion of the screen. The colored dot next to "Selected Process Is Running" indicates if the selected process is accumulating time. Green means the process is running and accumulating time. Red means the process is not running and is not accumulating time. This is controlled by the weekly work schedule located in the "Process Update" – "Work Schedule" main screen menu. The other colored dot next to "Database Connection Established" should always be green indicating the database is connected.

Selected Process Is Running 🥥		
Database Connection Established 🥥		
3/3/2019 7:53 PM		

To exit the program: click on the File menu and choose Exit.

Operator Log In

Click on the "Current User" control. A user log in screen appears. Select the username, type in the password (case sensitive) and the "OK" button will become active to log in.

User Name		
admin		
Password		
Change Password		
Ok Cancel		

Changing the Password

To change the password, enter the current password on the login screen and the "Change Password" option will become visible, click the box then click "OK" to get to this screen:

Confirm Password	Password	
	Confirm Passwo	ord

Enter the new password, type it again to confirm, then select "OK" to change the password.

Operator Log Out

To log out click on the "Current User" control while logged in and the following prompt will appear:

Ľ		×
	admin logging out.	
	ОК	

Performing Due Analysis

Select the process and station that is due for analysis.

PROCESSES	STATIONS	Show Station Numbers
 × Lane 2 - Preplater × Lane 3 - Plater × Lane 2 - Rack Strip × PH Calibration East Hoist Line × Strip Etch Strip 	Copper Strike X Bright Acid Copper 1 Bright Acid Copper 2 Bright Acid Copper 3 Bright Acid Copper 4 Bright Acid Copper 5 Bright Acid Copper 6 Satin Nickel 1 Satin Nickel 2 Semi-Bright Nickel 1 Semi-Bright Nickel 2 Semi-Bright Nickel 3 Semi-Bright Nickel 3 Semi-Bright Nickel 3 Semi-Bright Nickel 3	

Optionally station numbers can be displayed to the right of each station by selecting the "Show Station Numbers" checkbox.

Select the "Events Due Now" radio box to display the events due.

Events Due Now
 OUpcoming Events

Click the line that contains the text "ANALYSIS"

Station #EC04 (748 Microetch) of the Electroless Copper process due for DUMPING: 120.00 Square Feet past due ANALYSIS due for Sulfuric Acid (PC Grade), Station #EC04 (748 Microetch) of the Electroless Copper process: 1.02 hours overdue

Then the Component Analysis screen will appear.

Scheduled Analysis

Component Analysis



All the components within the station that have an analysis trigger are listed in the above analysis screen. The input units, concentration units, add units, spec window, and comments are also listed for each component. If the component has a complex formula, that component name is shaded in yellow. The components that have a scheduling symbol associated with them show white in the input column. Components that are added through conditional formatting will have a dark gray background in the input column. These components do have an input option, but will be given an add amount from another component. See the <u>Conditional Add</u> section for more information.

Clicking in the input column will bring up the following screen associated with the row that was clicked on.

Analysis Entry

Enter the value from analysis. The concentration and add amounts are calculated. Should the calculated add be less than the add threshold value, the add amount shown will be zero.



Edit Add Amount

An option to edit the add amount is available for components that do not have a complex formula. The option to edit the add amount is only available for level 5 users. More information about levels can be found in the "Users and Permissions" section.

Station #EC13 (Electroless Copper) of the Electroless Copper Process
Cuposit "Z"
Enter Your Measured Value Here>
Concentration> 0.0000 g/l
Delta> 8.000
Add Threshold 0.0 liters
The amount for you to add is>
ANALYSIS PROCEDURE
OK Cancel

The calculated add amount is set to zero and "The amount for you to add is" control can now be edited. Type in the add amount and click on the "OK" button.

Note: When editing the add amount the target value for this add is calculated based on the edited add, and replaces the default target value in the log entry.

The analysis screen now appears with the information from the analysis entry.

Station #EC13 (Electroless Copper) of the Electroless Copper Process										
Component	Input	Unit	Concentration	Add	Spec Window	Comments				
Cuposit "Z"	1.7000	mls	6.8000 g/l	1.4 liters	6.400 to 10.000					
Cuposit "A"		Absorbance			1.800 to 2.400					
Cuposit "Y"		Mis			2.750 to 5.000					
Cuposit "R"		MIs			28.000 to 34.000					
Weight Gain		microinches			50.000 to 70.000					
Specific Gravity		S.G.			1.040 to 1.150					

The concentration from analysis is displayed in green if it is within the spec window or red if outside the spec window. The calculated add appears in the add column. If the add is below the add threshold value for the component, the add will be zero.

Other options available from this screen are accessed by clicking anywhere on the row outside of the input column. The following menu will appear.

Station #EC13 (Electroless Copper) of the Electroless Copper Process									
Component	Input	Unit	Concentra	ition	Add	Spec Window	Comments		
Cuposit "Z"	1.7000	mls	6.8000 g/l		1.4 liters	6.400 to 10.000			
Cuposit "A"		Absorbance				1.800 to 2.400			
Cuposit "Y"		MIs				2.750 to 5.000			
Cuposit "R"		MIs				28.000 to 34.000			
Weight Gain		microinches	Procedure			50.000 to 70.000			
Specific Gravity		S.G.	Show Formula			1.040 to 1.150			
			Maint. Add						
			Exclude Data						
			Cancel						
<u></u>	CANCEL								

Analysis Menu Options

Procedure

This will bring up the analysis procedure for the component.



Trend Chart

This will display a trending chart for the component.



Show Formula

This allows you to view the formula used to calculate the concentration and add.



Maintenance Add

The following screen appears when choosing maintenance add.

Station #EC04 (748 Microetch) of the Electroless Copper Process MAINTENANCE ADD FOR Sulfuric Acid (PC Grade)
Enter the Amount of Your Add Here>
FINISHED CANCEL

Enter the add amount and click on the "Finished" button. The add will appear for the component with "(Not Analyzed)" appearing in the concentration column. It should be noted that the analysis trigger is NOT reset. The only way to reset an analysis trigger is to perform the analysis.

Exclude Data

Choosing this option will place "(NOT INCLUDED)" in the comment column. This will cause the data entry for this component to be excluded from all SPC data sets and calculations. This is designed for analysis being performed to start up a process. This should only be used when no product was processed with this bath concentration.

Comments

This option will bring up a screen where you may type in any comment to be associated with this analysis. This is for a general comment and is not for Out of Spec comment or Out of Control corrective action. It will however appear with this data point in the trending charts in the component history.



Click the "OK" button.

The next thing that happens depends on how the station is setup. If the "Automate Add Printout" option is checked in the station setup, the adds are automatically printed out. The basis for determining whether to include an add in the printout is done by comparing the add amount to the "Add Threshold" value. If any of the adds are equal or greater than the add threshold, the following prompt will appear listing each component that meets the criteria.

Х.	×
Add Slip Issued.	
Sulfuric Acid (PC Grade)	
OK	

If the "Automate Add Printout" is not checked in the station setup, the following screen appears after exiting the analysis screen.



This screen lists the calculated concentration and adds for each of the components that were analyzed. For maintenance adds, the component will show that it was not analyzed. To confirm the add is to be made to the station, click on each line ("ADD ISSUED" will appear). Click on the "Issue & Print Add Slip" button to print out an add sheet.

Note: If the lab tech fails to click on the line to confirm that an add is to be made, Lab Wizard will not log the add nor will it be included in the add sheet. It will, however, log the analysis and concentration and reset the trigger for that action.

Real Time SPC

After closing out the print add sheet screen or clicking the "OK" button on the prompt, Lab Wizard retrieves data from the log files for each component analyzed. The control limits are calculated and compared to the concentration from analysis. The spec limits are also compared with the concentration. If the concentration is out of spec or out of control, the following prompt appears.



This prompt informs the operator of an out of spec or out of control condition. If the concentration is out of control, the SPC rule or rules that are violated are listed. Click on the "OK" button and the following screen appears.



A control chart is displayed with the last data point being the concentration of the analysis just performed. The data interval used is dictated by the number of days entered in the SPC setup. The dashed red lines are one standard deviation apart. The solid red lines are the control limits. When an out of spec condition occurs, an out of spec cause must be chosen before exiting this screen. To apply an out of spec cause, click on the drop-down list "Select OOS Cause Here Before Exiting" and click on the appropriate cause. If an out of control condition occurs, the operator can type in the comment in the text box at the bottom of the screen. This is optional. If the corrective action has not been determined, leave the default "Corrective Action Unknown" in the text box.

If the out of spec cause is not listed in the out of spec drop down list, click on "Add New Cause" option at the bottom of the list. The following screen appears.

Analysis too far apart				
Analysis overdue				
Tank level too low				
Tank level too high				
Concentration high due	to previous add			
Previous add not made				
POSSIBLE PROBLEM WIT	H RECTIFIER			
New Bath: Make Up of N	New Bath is High.			
Due for dump				
New Bath: Make Up of N	New Bath is Low			
High tempreduce etch	time			
BATH OVERFILLED				
entered wrong number				
NEW BATHSp.G. norma	ally low			
Not enough ventalation,	PH high			
maint.add possibly not r	nade			
plated too long				
Controller not keeping u	p with pump.			

Type a new cause into the text box and click on the "Add New Cause" button. The new cause is applied to the data point and also added to the bottom of the list of causes.

The control chart will normally only appear after an analysis that is either out of spec or out of control. However, if the option "Display control chart after every analysis" is checked in setup, the control chart will appear after every analysis. If the action limits are enabled and the concentration is beyond either limit and not beyond the control limits or spec limits, a prompt will appear containing instructions for that situation.

Scheduled Station Make-up

When a scheduled station dump is due, it will appear in the "Events Due Now" window.

Station #EC01 (Conditioner 3320) of the Electroless Copper process due for DUMPING: 2503.00 Square Feet past due	100
	Ĵ

Click on the line that shows the station is due for dumping and the following screen appears.

Stati	on #1001 (Hole Prep) o	f the Cuposit process	
Station Recipe			
Cuposit Z 25.50 L CIRCUPOSIT Hole Prep 211A 39.75 L			
· · · · · ·	Print & Issue	Cancel	

This screen shows the station recipe for a new make-up. Click on the "Print & Issue" button to print out a make-up sheet. When the "Print & Issue" button is clicked, the station make-up is logged along with the adds required to make-up the station and the make-up trigger is reset.

To perform an early analysis or station make-up, Click on the "Upcoming Events" option.



Click on the appropriate line and continue as described in the previous sections on scheduled analysis and station make-up. Note: The station trigger is reset for make-up and component triggers are reset for each component included in the make-up.

Tracking Number

This number is the last number printed for an add or makeup sheet. The number is cumulative and cannot be reset.

Tracking # 000015

Main Screen Menu

File	Setup	History	Process Update	Reports	Devices	Help

File

Exit: Shuts down the program.

Setup

Process Setup: Opens the main process setup screen.

Users and Permissions: Allows adding, deleting, and editing users and passwords.

Dashboards: Opens the dashboards screen. See the Dashboards section for details.

History

Process History: Opens the process history screen.

Station History: Opens the station history screen.

Component History: Opens the component history screen.

PM History: Opens the preventative maintenance history screen.

Advanced History: Opens the advanced history screen.

Device Alerts History: Sensor hardware integration COMING SOON.

Process Update

Product Through-put: Allows entry of process through-put.

Work Schedule: Allows changing process time accumulation schedule.

Reports

Events Status Report: Opens the events status report screen.

Events Completed Report: Opens the events completed report screen.

Out of Spec Report: Opens the out of spec report screen.

Cpk Report: Opens the Cpk report screen.

Preventive Maintenance Report: Opens the preventative maintenance report. **Station History Report:** Opens the station history report screen.

Devices

Sensor hardware integration COMING SOON.

Help

Version: Displays the current version of Lab Wizard.

Setup

Users and Permissions

Choosing the above menu displays the following screen.

USEIS	User Management
admin 🔺	User> admin
Brady	Level> 5
Sarah	Password> ****
Reports	Department> all
Operator	
	Change Password
	permissions. Each nighter level inhelds the permissions of the previous levels.
	Level 1 - View history & reports
	Level 2 - Handle issued slips & PM tasks
	Update Permission Level Level 4 - Access to process update menu
	5 Level 5 - Full admin access to everything
1	

Clicking on a name in the user list will display the password level assigned to that person. The password is not displayed, but can be changed by typing the new password in the password control.

User Levels

The user levels are used for selectively restricting program access for individual users. The lower the user level the more restrictive the access. Level 5 users have all program access.

Level 1: Allows viewing of all histories and reports.

Level 2: Allows operation of the "Add and Make-up Issued" and "Preventive Maintenance" controls on the main screen.

Level 3: Allows for analysis.

Level 4: Allows updating process through-put and process work schedule. Editing of the station history within the "Station History" and corrective action within the "Control Chart" is also allowed.

Level 5: This is the account which has access to all areas of the software. The default password is blank, you can hit the backspace key and "Ok" to log in. From this point you can enter "Users and Permissions" to set the admin password and add additional users.

Note: You cannot delete the admin account, if you need to reset the admin password please contact the Lab-Wizard support team and we will issue a password.

Add User

Click on the "Create New User" button and the following screen appears.



Type in the user name, password, and assign a level. Click on "Save" to save and return to the "User Management" screen. You should now see your newly created user on the list.

Delete User

Select the name to delete. Click on the "Delete User" button. A window will appear to confirm deleting the selected user.

Click on the "X" in the top right of the window to close the "User Management" window and return to the main screen.

Process Setup

Only level 5 users can access the setup screen.

rile con setup Preventive Maintenance Printing Email Backup/Restore Utilitie		
The set of	Stations Station OPTIONS Chrome Strip Important Control of the strip of the str	Components COMPONENT OPTIONS Nitric acid Imetal Imetal Imetal Analysis / Units / Spec Limits SPC / Control Chart Action Limits / Procedure Action Limits / Procedure Analysis Triggered by: Hours Product Run Through Process Imetal Re-analyze after Add Reduct Scippert Re-analyze after Add Malerup Steppert Bath Concentration Units Unit for analysis Unit for analysis Unit for new station make-up Malerup Processor Add Precision Inits Concentration Constant Prompt List Technicus with Technicus with
Friday Scheduled Times: Saturday Scheduled Times:		Unit for ranalyss Unit for new station make-up Make-up Precision mis

The setup screen shows the details of how each process is structured. Choosing a process, station, and component in the list boxes displays the setup values for each. **Nothing can be changed from this screen**. To add, modify, or delete a process, you must use the "Process Options" drop down menu. To add, modify, or delete a station, you must use the "Station Options" drop down menu. To add, modify, or delete a component, you must use the "Component Options" drop down menu. The green drop down menus have a corresponding text box which will change to the value based on the data that has been entered for that selection.

File	Edit	Setup	Preventive Maintenance	Printing	Email	Backup/Restore	Utilities
Mon-	. Ontio	•					
Ment		ns					
File							
	Cance	l					
	Save a	nd Exit					
Edit							
	Pareto	Causes					
	Globa	l Constan	ts				
Setup	1						
	User N	/Iode					
	Event	Triggerin	ng Symbols				
Preve	ntive M	aintenan	ce				
	Prever	itive Mai	ntenance				
Printi	ing	_					
	Add T	emplate					
	Make-	up Temp	late				
	Out of	Spec Ter	nplate				
Emai	l	_					
	Email	Server					
	Email	Addresse	es				
	Email	Recipient	ts				
	Test E	mail					
Backı	ıp/Resto	ore					
	Backu	р					
	Restor	'e					
1.	Impor	t Migrati	on File				
Utiliti	ies						
	Remot	e Config					

All other program attributes are accessed through the menus at top of the screen.

The Process Options drop down menu has the following:

Add Process Modify Attributes of Selected Process Delete Process Duplicate/Rearrange

The Station Options drop down menu has the following:

> Add Station to Selected Process Modify Attributes of Selected Station Delete Station from Selected Process Duplicate/Rearrange

The Component Options drop down menu has the following:

> Add New Component to Selected Station Modify Attributes of Selected Component Delete Selected Component Duplicate/Rearrange

For a detailed description of the above menu options, refer to the <u>Lab Wizard Setup</u> section.

History

Process History

The process history screen displays a chart of the product throughput for the process highlighted in the list box. The period of time shown in the chart is determined by the setting of the start date and the end date (default is the last 30 days). Choose the process and time interval then click on the "Execute Query" button and the appropriate data is graphed. The "Total Amount Processed Through Line" window indicates the total amount with units for the time period selected. To view the throughput for other processes, click on the process in the list box.

PROCESS		
Electroless Copper Automated Plating Brown Oxide Desmear Manual Plating Nickel/Gold Plate Pumice Pre-Clean SES Line	Start Date	DUERY End Date 03/09/2019
	Total Amount Processed Through Line 9912.00 Squa	are Feet Log Entries Found
PRODUCT PROCESSED		
2800.0-		
2600.0		
2200.0		
1800.0 -		
1400.0		
1200.0-		
800.0 -		
400.0		
-0.0- 02/07 02/08 02/09 02/10 02/11 02/12 02/	13 02/14 02/15 02/16 02/17 02/18 02/19 02/20 02/21 02/22 02/23	ດນ້24 ດນ້25 ດນ້26 ດນ້27 ດນ້28 ດນ່າາ ດນ່າວ

Clicking on <u>VIEW DAILY ANALYSIS BY PROCESS</u> will show details associated with a process for a given day. This screen can show data on a single day for any number of processes. The report types are analysis, adds, make-ups, and all. Included with the analysis type is the option to only display out of spec and out of control data.

To obtain a report that lists all of the stations and components regardless of activity for the day, choose the "include no data table entries" option. Multiple process reports are achieved by holding down the shift key while selecting additional processes with the mouse. After the selections have been made, click on the **execute Query** button to display the data.

Process Process Process ID and 2 - Preplater Lane 2 - Preplater Lane 3								А 	REPORT TYPE ANALYSIS ADDS MAKE UPS ALL	Execute Query DATE 09/15/2021]	Include "NO DATA" table entries Only Display Out of Spec/Control Points	Copy to Clipboard
Process	Station	Station #	Component	Date	Time	Event Info	Amount Overdue	Technician					A
<u> </u>													
<u> </u>													
<u> </u>													
-													
L													
4													Þ

The information is displayed as follows.

- 1. Process
- 2. Station
- 3. Station Number
- 4. Component
- 5. Date
- 6. Time

Event Information (Depending on the report type) includes:

a. Analysis concentration with out of spec causes, out of control corrective action, and general comments.

- b. Add amount
- c. Make-ups
- d. All the above.
- 8. Amount overdue
- 9. Technician

To edit or print the data, click on the "Copy to Clipboard" button to paste the data into another program.

Clicking on the "View OoS Causes For All Processes" button brings up the following screen.

Out of Spec Causes Pareto Screen



This screen displays the out of spec causes used for all processes. The time interval is chosen by the month or months. The out of spec causes are listed by "% occurrence" or "frequency" which can be toggled by pushing the button.

Station History

The station history screen displays the log file entries for the selected station with the most recent file listed first and the oldest entry listed last. Choose the process and station from the list boxes. Select the "Start Date" and "End Date" (default is 30 days) interval then click on the "Execute Query" button to retrieve the log file information. The displayed log file entries are date, time, action taken, operator, result, out of spec cause (if any), out of control corrective action (if any), and general comments.



Note: The text box will auto size depending on the number of "data entries found".

To print out the displayed data, click on the "Print Log" button. Click on the "Edit Mode" box to edit the log entries. This function requires a level 4 or 5 user to be logged in. Locate the line that needs to be changed and click on that line.

The following screen appears.

	Analysis Fields					
Log Information (Read Only)	Value Unit Lab Tech D.1000 admin Out of Spec Comment Fields					
Process Electroless Copper	Bath needs to be replenished with new solution.					
Station Conditioner 3320	Corrective Action Fields					
Component Conditioner 3320	N/A ^					
	Comment Field					
Ck Dk	- Delete Cancel					

This screen displays the fields of the log entry, the fields on the right-hand side can be edited. To edit an entry, click in the field that you want to edit and enter the changes. If the entire entry is to be deleted from the log file, click on the "Delete" button, otherwise click on the "OK" button to save the changes. The changes will not appear in the station history screen until the "Execute Query" button is clicked again.

Note: The editable fields change depending on whether the log entry is for an analysis, add, or make-up. This also edits the database.

The station setup can be viewed from this screen by clicking on the "Station Setup" button. The following screen appears.

Click on the "Exit" button to leave the station history screen and return to the main screen.

Station Setup

The information in the station setup is: station name, station number, station size, units describing station size, Automate Add Printout, Option to require an analysis after a station makeup, trigger method for new makeup, and number of units required to trigger new station makeup.

Station Name			
Conditioner 3320			
Station Number	Station Size	Unit Describing Station Size Gallons	Automate Add Printout
Trigger Station Make-up	by: Product	Hours 0.00 Product Run	Through Process 41500.00
Add Instructions]		
	X	EXIT	

This screen is only to view the component settings, to configure the component see the "Process Setup" section. The only setting that can be toggled is the drop down menu to display the "Add

Instructions"

Or the "Makeup Instructions"



Click on the "Exit" button to return to Station History then click on the "Exit" button to leave the station history screen and return back to the main screen.

Component History



The component history screen displays two charts. Click on the process, station, component, and adjust the time period (30 day default) or choose the option to display the latest specified number of data points. Next click on the "Execute Query" button to display the data. The "# of Data Points" indicator displays the number of data points contained in the concentration chart. The two charts display the following information.

1. Concentration chart:

- a. Plots the concentration of the component and the target value if an add was made.
 Note: "Have control chart display target value after every add" must be checked to display target value. This setting is found within the process setup screen.
- b. Plots the upper and lower spec limits for the component concentration.
- c. Plots the spec center line.
- d. Displays the average concentration for the specified time period.
- e. Displays the Cpk for the specified time period.
- f. Plots the upper and lower action limits along with the upper and lower limit values if the action limit option is enabled.

2. Adds chart:

- a. Shows each add that was made for the specified time interval.
- b. Indicates the total amount for the adds made in the specified time interval. When add and make-up units are different, the drop down menu shows the total for each unit.

On the left side of each chart there is a cursor which can be dragged over a data point, this displays the log information for that data point in the text window at the bottom of the chart. The information obtained from the log file for the "Concentration Chart" are: date, time, component, action taken, operator name, concentration, out of spec cause (if any), out of control comments (if any), and general comments (if any). The information obtained from the log file for the "Add Chart" are: date, time, operator name, and the name and amount of the component added.

Additional SPC charts

Charts are accessed with the buttons at the top of the concentration chart.

Soc Oos Pareto Scottrol Chart

- 1. Out of Spec Pareto Chart
- 2. Cpk Plot
- 3. Control Chart

SPC Printout

SPC Printout

Provides a print out of the following on a single page.

Concentrations Trending Chart: Plots the upper and lower limits with the concentration data. Any out of spec data is numbered for reference in the comment box.
 Out of Spec Comments: Lists any Out of Spec comments for out of spec data point in the trending graph.

3. **Concentration Control Chart:** Plots the upper and lower control limits with the concentration data. Any out of control data points are numbered for reference in the comment box.

4. **SPC Rule Violation & Corrective Action:** Lists the SPC rule violations and the corrective action for any out of control data points in the control chart.

5. Moving Range Chart: Plots a moving range chart

6. Process Capability Plot: Plots the process capability curve
The top chart labeled "Concentrations" is the concentration trending chart. Out of spec data is numbered and the corresponding out of spec cause and any general comment is listed in the text box to the right of the chart.

The "Concentration Control Chart" numbers all data points that are out of control. These numbered points are listed in the comments text box, to the right of the chart, along with the SPC rule violation, corrective action, and general comment for each data point.

Below the control chart is the "Moving Range Chart". The bottom chart is the Cpk Plot or the "Process Capability" chart. Click on the Print button to print out the page and return to the Component History screen.

Note: The data set is determined by the start and end dates in the component history screen. Any changes made to the Cpk Plot or the Control Chart will automatically be passed on to the SPC Printout.



Cpk Plot



This plot is very useful in determining if the process is centered and if the frequency of analysis is correct. The following information is displayed in the chart.

- 4. Histogram of the data (interval picked in the component history screen).
- 5. Upper Spec Limit
- 6. Spec Center Line
- 7. Lower Spec Limit
- 8. Upper Control Limit
- 9. Data Mean
- 10. Lower Control Limit
- 11. Normal Probability Distribution Function

Control Chart



Displays two charts:

- 1. Control chart with associated Histogram.
- 2. Moving Range chart with associated Histogram.

Control Chart: Out of control data is displayed as red data points.

1. Concentration Control Chart: Contains the following.

- a. Plots concentration, upper control limit, and lower control limit and control limits center line. The dashed lines are the first and second standard deviation lines.
- b. Top Text Box: Indicates how the control limits are determined.
- c. Bottom Text Box: Provides information about the data point that the cursor is on.
 - i. Point is in control
 - ii. Point is out of control, which SPC rules are violated and corrective action.
- d. Histogram of data displayed on the Y axis with the number of data points in each bin located on the X axis.
- e. Add/Modify out of control comments. The "add or modify check box" is only visible when the cursor is on an out of control data point.
- 2. **Moving Range Chart:** Out of control range is displayed as red points.
 - a. Plots the range, range mean, and lower and upper control limit.
 - b. Select the number of data points per range calculation.
 - c. Histogram of range data plotted on the Y axis with the number of data within each bin plotted on the X axis.

Editing Corrective Action

To edit the out of control corrective action comment, place the cursor on the OoC data point. The Edit out of control Comment control pictured appears.

Click on the control and the following screen appears. Note: requires a level 4 user to access.

Click in the text box to edit the corrective action for the data point selected. Clicking "OK" edits the log file and database to change the comment and returns to the control chart screen.

Process		Station		Component	_
Electroless Copper		748 Microetch		Sulfuric Acid (PC Grade)	
	You are adding/editing	g a comment for the for the	following analysis		
	Time and Date	03/06/19 Control Char	t value		
ur corrective action					
ake-up a new bath					

Note: Placing the cursor on an out of control data point that is a result of an add will not enable the Add/Modify out of control comment control. This is because only analysis data points have corrective action comments, add entries do not.

Chart Controls

Below the charts are the following controls. Cursor Control



The three sections above display the cursor name, date and value of data point where the cursor is located.

 $\diamond \diamond$ Clicking on either button steps the cursor in that direction.



H R M This control determines how the mouse functions with the chart.

Here Allows the mouse to drag the cursor.

🖉 Zoom control, clicking this displays the following options.

Zooms in an area of the chart.



Zooms in an area of the chart on the x-axis.



Zooms in an area of the chart on the y-axis.



Zooms in or out to autoscale the chart.



Zooms in. Holding shift will switch to zooming out.

Zooms out. Holding shift will switch to zooming in.

Mallows the entire contents of the chart to be moved by clicking and holding down the left mouse button while moving the mouse. The cursor will change to a hand when this is active.

Out of Spec Pareto Chart

The left chart is a histogram breakdown of causes.

Process	Station	Component	
Electroless Copper	Conditioner 3320	Conditioner 3320	List By % occurance
			Pareto Cause
Pareto chart 9.0 8.0 7.5 7.0 6.5 6.0 5.5 5.0 4.5 5.0 5.0 5.0 5.0 5.0 5.0 5.0 5			radio Cadse CASSE Controller not keeping up with pump. 66.67 plated too long of or rework also the solution of the solutio
25- 20- 1.5- 1.0- 0.5- 0.0- 0 i	Histogra	4 5	

On the right there are 2 options available to view the causes which can be selected by pressing the button.

The options to view the causes are:

- By the percentage of each occurrence.
- By frequency of occurrences.



Component Setup

The component setup can be viewed by clicking *component Setup* the button.

Analysis Setup Analysis Triggered by: Time	Re-analyze after Out of Spec Analysis Trigger Make-up based on adds
Component Name Conditioner 3320 Product Run Through Process 0.00 Hours 24.00 Make-u	Setpoint Re-analyze after Add
Unit Setup Unit describing bath concentration normality Unit for adds liters Add	hreshold 0.000 Add Precision 0.0 🔻
Unit for analysis mis Unit for new station	make-up gallons Make-up Precision 0.0 V
Control Limits Lower Limit 0.450 Target Value 0.500 Upper Limit 0.550 Constants	Concentration Constant 0.100 Add Constant 90.800 Amount for new bath make-up 12.0
Instructions Prompt Lab Technician with the instructions below if component concentration is: < 0.00 Instructions	
SPC E Have control chart display target value after every add Upper Control Limit 0.600 SPC Rules Display control chart dire every analysis Lower Control Limit 0.400 0.000 Manually Define Control Chart Parameters Moving Range Upper Control Limit 0.000 Sindude in Cpk Report Moving Range Average 0.000	☑ Flag data point when any single value from analysis is above or below the mean by three standard deviations ☑ Flag data point when 2 out of 3 consecutive points fall outside two standard deviations below or above the mean ☑ Flag data point when 4 out of 5 consecutive points all appear below or above one standard deviation from the mean ☑ Flag data point when ● 7 ● B points in a row on one side of the mean Number of days to check for SPC chart after each analysis
Action Limits Enable Action Limits Enable Action Limits Example Action Limits Example Action Limit Example Action	

This screen is useful for the quick review of the component being viewed.

Note: The component can only be viewed from this screen, to edit the component see the <u>Process Setup</u> section.

Preventive Maintenance History

The preventive maintenance history screen allows easy tracking of when a preventive maintenance is being completed.

Select a given PM list in the left portion of the screen to show the history for that item. The default is to only list the latest 32 entries, the number of entries can be changed with the "Maximum Entries To Display" option in the top right of the window. The "Search" button allows for searching the text for a specific PM, all PMs



that match the searched text will be displayed. The search criteria can be cleared by clicking on the "Clear Search" button that will be in the place of the "Search" button.

Advanced History

The advanced history viewer allows for graphing multiple plots on the same graph for easier comparisons. The options include Device Signal Plot, Component Concentration Plot, and Component Addition Plot. Any

9/12/2021 3 57/00 000 PM						21.6
• • • • • • • • • • • • • • • • • • • •						21.5
autorate a transmission and						21.4
+ 112/2021 35350000 PM						21.3
						721/2
Active Plots						21
🗹 conc_Sulfuric Acid_oz/gal						20.9
						20.8
						20.7
						20.5
						20.4
						20.3
						20.2
						20. 8
						19.9 2
						19.8 g
and the second sec						19.7 6
Manage Plots						19.5
👍 Add Device Signal Plot						19.4 8
- Add Component Concentration Plat						19.2
						19.1
💠 Add Component Addition Plot						19
Remove Plot						18.8
						18.7
Graph Tools						18.5
Giapir roois						18.4
🕭 Re-Initialize 🔚 Print						18.3
						-18.2
Zoom Out Copy to Clipboard						18
						17.9
						17.8
2009 03:06:47	AM 12/05/2011 12	500:00 AM 12/04/2013	12/04/2015	2:00:00 AM 12/03/2017	2:00:00 AM 12/03/2019 1	2.00:00 AM 09/15/2021 10:34:13 AM
			Tim	e .		

combination of these options can be plotted for a given time period on one graph with the key listed under the "Active Plots" section on the left side of the screen.

Device Alerts History

Sensor hardware integration COMING SOON.

Process Update

Product Through-put

Choose this when you want to update process throughput at any unscheduled time. The first screen prompts you to pick a process for updating. Select the process and then click on the "OK" button.



The following screen shows the history of entries and asks for the new amount to be entered. After the entry is made, click on the "OK" button to return to the main screen.

Process Name Lane 2 - Rack Strip NO DATA YET FOR THIS PROCESS	This chart shows the amount of product processed through each station since the last time the station was dumped.					
	Station	Product Processed	Units			
	Chrome Strip	0.00				
	Nitric Acid 1	0.00				
	Nitric Acid 2	0.00				
	Nitric Acid 3	0.00				
	Nitric Acid 4	0.00				
× .						
Enter the amount of product that ran through the process since the last amount was entered above.						
🥪 Ok 🛛 🔀 Cancel						

Work Schedule

The work schedule is used to set up the time intervals for each process to accumulate time. Time triggers use this accumulated time.

Note: The program only accumulates time while Lab Wizard is running.

Process Electroless Copper Automated Plating Desmear Manual Plating Nickel/Gold Plate Pumice Pre-Clean S.F.S. Line Hot Air Level Control de Analisis Work Schedule Click on the "enable" button to make a certain day a working day. Enter the hour the process starts up and the hour the process shuts down. SUNDAY DISABLE START 7.0 FINISH 17.0 MONDAY ENABLE START 📮 7.0 FINISH 🔒 17.0 DISABLE START - 7.0 FINISH 17.0 TUESDAY ENABLE START = 6.0 FINISH 20.0 WEDNESDAY THURSDAY ENABLE START = 6.0 FINISH 20.0 FRIDAY START 🕀 7.0 FINISH 🔒 17.0 ENABLE START 🕀 5.0 SATURDAY FINISH 17.0 DISABLE

Save Save

Z Cancel

Select the process to schedule the process run time. Click on the Enable/Disable button to setup the days of the week the process is running. Enter the start and finish time for each day (24 hour settings). Click on the "Save" button to save the new schedule and exit.

Reports

Events Status Report

The content of the event status report is determined by what processes you choose, the report type, and the number of minutes to look ahead. Once the selections have been made click on the "Execute Query" button to display the information. The report is sorted by process. Clicking on the heading of the column to be sorted can change this.

	Process			R	EPORT TYPE		
Event Status Sorted By TO SELECT MULTIPLE PROCESSES THE SHIFT KEY WHEE CLICKING WI	y Process HOLD DOWN HOLD DOWN TH YOUR MOUSE Lane 2 - Preplater Lane 2 - Preplater Lane 2 - Rack Strip PH Calibration East Holst Line Strip Etch Strip			EVENTS THA EVENTS THA OVE	ARE ALMOST DUE IT ARE RECENTLY DUE RDUE EVENTS ALL Minutes 60	EXECUTE QUERY	Copy to Clipboard
Process	Station	Station#	Component	Status	Calculations	Last Done	
Lane 2 - Preplater	Etch 1	22-23-24	Chromic Acid	overdue	13.68 hours overdue		1
Lane 2 - Preplater	Etch 1	22-23-24	Sulfuric Acid	overdue	13.68 hours overdue		
Lane 2 - Preplater	Etch 1	22-23-24	Trivalent Chrome	overdue	13.68 hours overdue		
Lane 2 - Preplater	Etch 2	25-26-27	Chromic Acid	overdue	13.66 hours overdue		
Lane 2 - Preplater	Etch 2	25-26-27	Sulfuric Acid	overdue	13.66 hours overdue		
Lane 2 - Preplater	Etch 2	25-26-27	Trivalent Chrome	overdue	13.66 hours overdue		
Lane 2 - Preplater	Neutralizer	34	<station dump=""></station>	overdue	6661.13 hours overdue		
Lane 2 - Preplater	Neutralizer	34	Hydrochloric Acid	overdue	12.67 hours overdue		
Lane 2 - Preplater	Neutralizer	34	Macuplex 9339	overdue	12.67 hours overdue		
Lane 2 - Preplater	Activator 1	41	Hydrochloric Acid	overdue	13.00 hours overdue		
Lane 2 - Preplater	Activator 1	41	Macitvate 360	overdue	13.00 hours overdue		
Lane 2 - Preplater	Activator 1	41	Tin (Sensitizer 78)	overdue	13.00 hours overdue		
Lane 2 - Preplater	Activator 2	42	Hydrochloric Acid	overdue	12.98 hours overdue		
Lane 2 - Preplater	Activator 2	42	Macitvate 360	overdue	12.98 hours overdue		
Lane 2 - Preplater	Activator 2	42	Tin (Sensitizer 78)	overdue	12.98 hours overdue		
Lane 2 - Preplater	Accelerator	45	Hydrochloric Acid	overdue	12.38 hours overdue		
Lane 2 - Preplater	Accelerator	45	Maccelerator 25	overdue	11.83 hours overdue		
Lane 2 - Preplater	Electroless Copper	48-49-50	Caustic (NaOH)	overdue	20.36 hours overdue		
Lane 2 - Preplater	Electroless Copper	48-49-50	Formaldehyde (HCHO)	overdue	20.36 hours overdue		
Lane 2 - Preplater	Electroless Copper	48-49-50	Ultradep 30A	overdue	20.36 hours overdue		
Lane 2 - Preplater	Electroless Copper	48-49-50	Ultradep 61B	overdue	2.65 hours overdue		
Lane 2 - Preplater	Electroless Copper	48-49-50	Specific Gravity	due now	0.38 hours overdue		
Lane 2 - Preplater	Electroless Copper	48-49-50	Plate Thickness	overdue	19.42 hours overdue		
Lane 3 - Plater	Satin Nickel 1	76	Nickel sulfate	overdue	65.11 hours overdue		
Lane 3 - Plater	Satin Nickel 1	76	Nickel chloride	overdue	65.11 hours overdue		
Lane 3 - Plater	Satin Nickel 1	76	Boric acid	overdue	65.11 hours overdue		
Lane 2 - Distor	Satin Nickel 2	77	Nickel culfate	overdue	65.50 hours overdue		

The generated report can be exported to Excel or copied to the clipboard to be pasted into another program by selecting either button in top right of the window.

Events Completed Report

The events completed report will display any add or make-up event that has been completed for the selected station. The report can be generated for just add events, just make-up events, or both add and make-up events.

processes	stations				
Lane 2 - Preplater Lane 3 - Plater Lane 2 - Rack Strip PH Calibration East Holst Line Strip Etch Strip *	Copper Strike			ds	Copy to Clipboard
Process	Station	Event	Date Completed	Operator	Time to Complete (min)
Lane 3 - Plater Co	pper Strike	Add	2021-09-15 10:45:23	admin	4067
Lane 3 - Plater Co	pper Strike	Add	2021-09-15 10:45:23	admin	4067
Lane 3 - Plater Co	pper Strike	Add	2021-09-15 10:45:23	admin	4067

Out of Spec Report

The out of spec report will display analysis that is out of spec for any or all processes during the date interval indicated by the start and end date.

Out of Spe	ec Report								
THE SHIFT KEY WHILE CLI Report	PROCESSES, HOLD DO LICKING WITH YOUR N	DWN MOUSE	Electroless Copper Automated Plating Brown Oxide Desmear Manual Plating Nickel/Gold Plate Pumice Pre-Clean SES Line				Set Date Set Date <u>Set Date</u> <u>Set Date</u> <u>Set Date</u> <u>Set Date</u> <u>Set Date</u> <u>Show Out of Control</u> <u>Show Excluded Data</u> <u>Show Excluded Data</u>	Export	Data
Process Sta	tation	Station #	Component	Spec Limits	Date	Time	Event Info	Amount Overdu	Technician 🔺
Electroless Copper 74	48 Microetch	EC04	Sulfuric Acid (PC Grade)	1.75 to 3.00	03/06/2019	12:27	Concentration = 6.1600 %, OoS Cause: Tank level too high	-79.56	admin
Electroless Copper 74	48 Microetch	EC04	Sulfuric Acid (PC Grade)	1.75 to 3.00	03/06/2019	13:40	Concentration = 0.5600 %, OoS Cause: bath was carbon treated Out of Control: Make-up a new bath	-78.80	admin
Electroless Copper 74	48 Microetch	EC04	Sulfuric Acid (PC Grade)	1.75 to 3.00	03/09/2019	17:34	Concentration = 5.6000 %, OoS Cause: High tempreduce etch time	-79.97	admin
Electroless Copper 74	48 Microetch	EC04	Sulfuric Acid (PC Grade)	1.75 to 3.00	03/09/2019	17:34	Concentration = 6.1600 %, OoS Cause: Not enough ventalation, PH high	-80.00	admin
Electroless Copper 74	48 Microetch	EC04	Sulfuric Acid (PC Grade)	1.75 to 3.00	03/09/2019	17:34	Concentration = 6.7200 %, OoS Cause: Bath needs to be replenished with new solution.	-80.00	admin
Electroless Copper 74	48 Microetch	EC04	Sulfuric Acid (PC Grade)	1.75 to 3.00	03/09/2019	17:35	Concentration = 7.2800 %, OoS Cause: New Bath: Make Up of New Bath is High.	-79.98	admin
Electroless Copper 74	48 Microetch	EC04	Sulfuric Acid (PC Grade)	1.75 to 3.00	03/09/2019	17:35	Concentration = 7.8400 %, OoS Cause: Due for dump Out of Control: Corrective Action Unkown	-80.00	admin
Electroless Copper 74	48 Microetch	EC04	Sulfuric Acid (PC Grade)	1.75 to 3.00	03/09/2019	17:35	Concentration = 8.4000 %, OoS Cause: Previous add not made. Out of Control: Corrective Action Unkown	-80.00	admin
Electroless Copper Co	onditioner 3320	EC01	Conditioner 3320	0.45 to 0.55	03/06/2019	13:12	Concentration = 0.1000 normality, OoS Cause: plated too long	-2.97	admin
Electroless Copper Co	onditioner 3320	EC01	Conditioner 3320	0.45 to 0.55	03/06/2019	13:31	Concentration = 0.1000 normality, OoS Cause: bath is being used for rework also	-23.68	admin
Electroless Copper Co	onditioner 3320	EC01	Conditioner 3320	0.45 to 0.55	03/06/2019	13:45	Concentration = 0.1000 normality, OoS Cause: Controller not keeping up with pump.	-23.77	admin
Electroless Copper Co	onditioner 3320	EC01	Conditioner 3320	0.45 to 0.55	03/06/2019	13:46	Concentration = 1.0000 normality, OoS Cause: Controller not keeping up with pump.	-23.98	admin
Electroless Copper Co	onditioner 3320	EC01	Conditioner 3320	0.45 to 0.55	03/06/2019	13:47	Concentration = 0.1000 normality, OoS Cause: Controller not keeping up with pump.	-24.00	admin
Electroless Copper Co	onditioner 3320	EC01	Conditioner 3320	0.45 to 0.55	03/06/2019	13:47	Concentration = 0.1000 normality, OoS Cause: Controller not keeping up with pump.	-24.00	admin
Electroless Copper Co	onditioner 3320	EC01	Conditioner 3320	0.45 to 0.55	03/06/2019	13:47	Concentration = 1.0000 normality, OoS Cause: Controller not keeping up with pump.	-23.98	admin
Electroless Copper Co	onditioner 3320	EC01	Conditioner 3320	0.45 to 0.55	03/06/2019	13:47	Concentration = 1.0000 normality, OoS Cause: Controller not keeping up with pump.	-24.00	admin
Electroless Copper Co	onditioner 3320	EC01	Conditioner 3320	0.45 to 0.55	03/06/2019	17:28	Concentration = 0.1000 normality, OoS Cause: Bath needs to be replenished with new solution.	-20.32	admin
						_			
						_			
						_			
						_			
						_			
						_			
						_			
4									

Clicking on the "Show Out of Control" control will include analysis entries that were out of control, but not out of spec, along with the out of spec entries. Clicking on the "Show Excluded Data" will include analysis entries that were excluded for the SPC calculations. Any column can be sorted alphabetically by clicking on the column title. The sort direction is determined by the position of the "Sort Data" button.

Table data can be copied to the clipboard by clicking on the "Copy to Clipboard" button. Click on the "Exit" button to return to the main screen.

Cpk Report

This is a Cpk (Process Capability Index) Report by process. Any combination of processes may be selected. Stations are only listed when there is a component within that station with the component attribute "Include in Cpk Report" checked.

	Hold down Ctrl key to select multiple pro	cesses						
	Electroless Copper Automated Plating Brown Oxide Desmear Manual Plating Nickel/Gold Plate Pumice Pre-Clean S.E.S. Line Hot Air Level Control de Analisis	Cpk Rej Number of du	ODORT sta points QUERY	Export To Excel Print Exit				
Process	Station	Component	Spec. Limits	Control Limits	Sigma	# Data Pts.	PCI or Cp	Cpk 🔺
Electroless Copper								-0.12
	Conditioner 3320							
		Conditioner 3320	0.450 - 0.550 normality	-0.201 - 1.129	0.222	25	0.08	0.02
	748 Microetch							
		Sulfuric Acid (PC Grade)	1.750 - 3.000 %	-1.810 - 9.158	1.828	25	0.11	-0.12
I	Catalana	Preposit Etch 748	0.700 - 1.750 g/l	NaN - NaN	NaN	1	NaN	NaN
	Cataprep	Cataprop 404	1125 1175 Sp.C	1 109 1 160	0.000	2	0.04	0.29
	Catalvet	Cataprep 404	1.125 - 1.175 3p.d.	1.106 - 1.102	0.009	2	0.94	0.50
	Catalyst	Catalyst 44	85 000 - 115 000 %	84 107 - 110 863	4.459	2	1.12	0.93
		Cataprep 404	1.150 - 1.185 Sp.G.	NaN - NaN	NaN	1	NaN	NaN
		Cataposit 449 Replenisher	4.000 - 7.500 g/l	2.590 - 7.910	0.887	2	0.66	0.47
	Rack Strip							
		Hydrogen Peroxide	3.000 - 6.500 Percent	NaN - NaN	0.000	0	Inf	NaN
		Sulfuric Acid	6.000 - 15.000 Percentage	NaN - NaN	0.000	0	Inf	NaN
	1% Sulfuric Acid							
		Sulfuric Acid (PC Grade)	1.000 - 5.000 Percentage	NaN - NaN	0.000	0	Inf	NaN
					_			
l					_	_		
l					_			
I								
					-			
					-			
								v
•								•

The "Number of data points" control sets the number of data points to query for. Click the "Execute Query" button to generate the report. If the number in the "Number of data points" field is less than the number queried for, there is not enough data or there are too many data points excluded from SPC. The data within this report contains the latest data recorded. To print out the table, click on the "Print" button. Clicking on the "Copy to Clipboard" button will copy the data so that it can be pasted into another program.

Preventive Maintenance Report

The preventative maintenance report lists all preventive maintenance items according to their date due. Items in red are overdue with the first item the most overdue. Next are the items in green that are due with the first item being the first to go overdue. Next are the items that are not yet due and they are listed in the order of those that will be due first. For a printout with color coded text, click on the "Print" button.

PM Item Name	Interval (days)	Days to Complete	Date Due
Nickel Sulfamate Adhesion Test- AMS 2424 Quarterly	30	-8	2019-03-03
Monthly Hydrogen Embrittlement - Electroless Ni		-8	
Monthly Adhesion Testing - Iow carbon steel- AMS 2405		-8	
Monthly Adhesion Test- Aluminum (AMS 2404, AMS-C-26074)		-8	
Fire Extinguisher Cintas, Annual Maintenance			
Digital Temperature Indicator Calibration			
Yearly Cyanide Scrubber Clean-up			
Check Inventory Stock Levels		-38	
Scrubber Clean up-Suite 104	180	1	2019-03-12
System Accuracy Test	90	1	2019-03-12
Transfer Filter Gold	60	1	2019-03-12
Crest Trusweep Ultrasonic Generator	365	3	2019-03-14
Branson 1200 Ultrasonic Bath	365	3	2019-03-14
Crest Ultrasonic Generator	365	3	2019-03-14
Crest TruSweep Ultrasonic Generator	365	3	2019-03-14
Branson 7000 Ultrasonic Generator	365	3	2019-03-14
Pressure Gauge Replacement	360	6	2019-03-17
Pressure Gauge For Replacement	360	6	2019-03-17
clean/calib of pH electrode of final discharge	90	7	2019-03-18
Fluke True-rms Multimeter w/backlight and Temp	365	8	2019-03-19
Check Electrical Connections (Group 2)	200	12	2019-03-23
Check electrical connections	200	12	2019-03-23
5 g Weight Replacement	365	15	2019-03-26
10 g Weight Replacement	365	15	2019-03-26
Hazardous Materials Business Plan (HMBP) (EH&S)	365	15	2019-03-26
Timer Calibration	365	15	2019-03-26
Digital Temperature Controller Calibration	180	15	2019-03-26
Digital Temperature Controller Calibration	180	15	2019-03-26
Digital Temperature Controller Calibration	180	15	2019-03-26
Digital Temperature Controller Calibration	180	15	2019-03-26
Thermocouple Replacement	180	15	2019-03-26
n na anna an an anna anna anna anna an	Loss	1	

Station History Report

The station history report displays all analysis and make-up events for the selected station. This report will list all concentrations and add amounts associated with that analysis on the same line for an easier viewing. The report can copied to the clipboard with the "Copy to Clipboard" button so that the data can be pasted into another program.

				Sta	ation Rep	ort				
Display	Non-Triggere	ed Components 🛛 🔗 Select Station	Components in this station							
Statio	n Informa	tion	Component Name	Target	Spec Rappe	Optimal Rappe	Analysis Frequency	Start Date/Time	End Date/Time	
Juno			Copper Sulfate	14.00 oz/gal	8.00-17.00 oz/gal	8.00-17.00 oz/gal	5 Davs	9/5/2021 2:58:28.000 PM	9/12/2021 2:58:28.000 PM	m
	rocess Lani	e 3 - Plater	Sulfuric Acid	20.00 oz/gal	17.00-23.00 oz/gal	17.00-23.00 oz/gal	1 Day	-		
		and Chailes	Chloride (HCL)	60.00 ppm	50.00-70.00 ppm	50.00-70.00 ppm	5 Days	02:56 PM 02:58 PM	02:56 PM	(2:58 PM
	Station Cop	persone	Surface Tension	65.00 dynes/cm	60.00+70.00 dynes/cm	60.00-70.00 dynes/cm	2 Days	09/12/21 09/05/2021 09/12/2	1 09/12/21 09/12/2021	09/12/21
s	ation # 56-	57	Filter Cartridge Changes	d 20.00 psi	1.00-50.00 psi	1.00-50.00 psi	20 Days			
			Anobe bags Changed	2.00 fr/8	100-300 R/a	1.00-3.00 h/8	120 Days	🛫 Exe	cute Query	
Stati	on Size	4200 Gallons								
Temp	erature							Copy To Clipboard	Print Exit	
			Δna ¹	lvses				Additions		
Date	Event	Copper Sulfate	Sulfuric Acid	Chloride (HCL)	Sui	face Tension	Copper Sulfat	e Sulfuric Acid	Chloride (HCL)	Operator
09-12-21		13.36 oz/gal	19.68 oz/gal	59.28 ppm	6	2 dynes/cm	168 pounds	5.47 gallons	30.96 mls	admin
										-

Devices

Sensor hardware integration COMING SOON.

Help

Version

Displays the current version of Lab Wizard.

Lab Wizard Setup

To enter the main process setup, click on "Setup" then "Process Setup" from the main screen menu. **Note: Only level 5 users have access to this screen.**

Adding a Process

From the setup screen, choose "Add Process" from the "Process Options" drop down menu. Click in the "Process Name" box and enter the name for your process. Next click in the "Product Measured in" box and choose the units that describe how the product being processed is measured. The "Product" trigger for this process will use this data if the product option is selected for the trigger mode. This applies to the station make-up and component analysis. If you are not going to use product through- put as a trigger, this field can be left blank. **Note: Make sure the spelling is correct because after leaving this screen the only way to change the name is to delete the process and start over.**



The pop-up screen schedule is the next step in setting up the process. The pop-up screen schedules when the operator will enter the amount of product that has been run through the process. *If the process will not have any station makeups or component analysis that is triggered by product throughput or a both time and product throughput, then the pop-up screen will not be used. To schedule the pop-up screen, highlight the day of the week in the "Weekday" list box, click on the button in the "Notification Times" window to enable, then click on the time box and choose the time. For each day of the week, you can schedule up to four daily pop-ups. The above procedure must be repeated for each day of the week. When all the days of the week are accounted for, click the "OK" button. The process now appears in the "Process" list box of the setup screen.

Checking the "Out of Spec Printout" box will cause an out of spec printout to be automatically printed anytime any analysis within the process is out of spec.

Adding Stations to the Process

Make sure the process that you want to add stations to is highlighted in the "Process" list box. From the Station Options drop down menu select "Add Station to Selected Process". Click in the "Station Name" box and type in the station name. Next type in the station number by clicking on the "Station Number" text box. Enter the volume of the station by clicking in the "Station Size" box and typing the numbers. Click in the "Unit Describing Station Size" box and choose the unit for station volume. Click in the "Trigger Station Make-up by:" and choose the trigger option for station make-up. This trigger will notify the lab tech when a new station make-up is due. The options available are:

- 1. **Time:** The number of hours of accumulated process time before station make-up is due.
- 2. **Product:** The amount of product processed before new station make-up is due. The unit of this trigger is the unit specified in "Product Measured In" of the process setup.
- 3. **Both:** This option uses time and product parameters for new station make-up. Notification of new station make-up is based on either option coming due.
- 4. **None:** With this option selected there will not be any notification of new station make-up and the option to print out a station make-up is not available.

Click in the box or boxes that appear by selecting "Trigger Station Make-up by:" (The boxes that appear depend on the trigger option. They are "Hours" or "Product Run Through Process" or both.) Enter the number in the box that specifies the amount of time and/or product run through process before notification of new station make- up.



Click the "Automate Add Printout" to automate the add printout for this station. Click on "Analyze after make-up to require analysis after a new make-up. The optimal operating temperature can also be set here so that it will be displayed on the station report. The drop down menu below the text box has two options, Add Instructions and Makeup Instructions. To enter text for either option, click the text box and type the instructions in the screen that follows.

Click on the "OK" button. The new station now shows up in the "Stations" list box. Highlight the new station, the settings for the station are displayed below the stations list box.

Adding Components to the Station

Make sure that the process and station that you are adding a component to are highlighted in the "Process" and "Stations" list boxes. Use the "Component Options" menu to click on "Add New Component to Selected Station". Click in the "Name of Component" box

and type in the name of the component. Note: Care should be exercised when choosing this name. It is recommended to have the component name be the same name as on the chemical container that is used in making adds or station makeup since this will be the name printed on add and makeup sheets.

Event Triggering Component Name Analysis Triggered by: Time Hours 0.00 Product Run Through Process 0.00	Make-up Setpoint 0 Trigger Make-up based on adds Re-analyze after Add Re-analyze after Out of Spec Analysis	Units Bath Concentration Units Units for Analysis Units for Analysis Units for Adds Units for Adds Units For New Bath Make-up
Component SPC Setup Have control chart dspla Display control chart dspla Display control chart afte	ıy target value after every add ır every analysis	Concentration Constant Concentration Constant Add Constant Add Constant Amount For New Bath Make-up 0 0
SPC Rules Image: SpC Rules	Manualy Define Control Chart Parameters Below Upper Control Limit 0.000 Lower Control Limit 0.000 Moving Range Average 0.00 Moving Range Upper Control Limit 0.00	Spec Window Lower Lint Target Value Upper Lint 0.000 Station Make-up Prompt Prompt Lab Technician with the instructions Instructions Instructions
Action Limits Action Limits Action Limits Dependent of action limits should be used to alert a technician with a should be used to alert a sho	Perfif: Inix will be set ton Limit 00 Optimum Range Image: Comparison of the set Image: Comparison of the set	r Lint Upper Lint The optimal operating range is not used in calculations. This data is only displayed in the Station Report to display the optimal operating range. Image: Constraint operation operatio

Component Setup

Event Triggering

Check the "Re-analyze after Out of Spec Analysis" to require another analysis after the add is made for an out of spec analysis. The trigger value is reset to due (0) after the initial out of spec analysis. To initiate a new station make-up after a set total amount of adds, click on "Trigger Make-up based on adds" option then enter the total add value in the "Make-up Set point" control.

Click in the "Trigger Analysis by:" box and choose the type of trigger for notification of analysis due. There are four options to choose from.

- 1. **Time:** Analysis due is determined by the accumulated process time since the last analysis or make-up. A time of "Inf" can be entered if analysis needs to be entered for this component, but no alerts triggered for when to complete the analysis.
- 2. **Product:** Analysis due is determined by the amount of product processed (the units selected by "Product Measured In" of the process setup) since the last analysis was performed.
- 3. **Both:** Analysis due is determined by either time or product, whichever comes due first.
- 4. **None:** Entering analysis data will not be allowed for this component.

Depending on which trigger mode is selected, click in the appropriate box and enter the interval between analyses.

Units



Click in the "Bath Concentration Units" box and type the units to be used for the concentration of this component. Click in the "Units for analysis" box and enter the unit used when performing analysis. Click in the "Units for Adds" box and choose the unit to be used for making adds to the station. **Note: This unit must be the same unit that was used to calculate the "Add Constant".** Choose the add precision for the add variable. Click in the "Units for New Bath Make-up" box and choose the unit to be used for the component when a new station make-up is required. This unit will be used in the recipe for new station make-up and will be printed in the makeup sheet. Choose the makeup precision for the makeup variable. Click in the "Add Threshold" box and enter the required add to issue an add sheet.

Note: If there is no unit corresponding to this component leave the box blank. For example, if the component is not used when making a new make-up, leave the units for station make-up blank. Both "Units for New Bath Make-up" and "Amount for New Bath Make-up" must have something entered for this component to be included in the make-up print out. To log adds in the log file for a station make-up, the "Bath Concentration Units" and the "Units for New Bath Make-up" must be filled out.

Component Constants



Click in the "Concentration Constant" box and enter the number that when multiplied by the measured value from analysis gives the concentration in the units specified in the "Bath Concentration Units" box, i.e. (measured value in units for analysis) x (concentration constant) = concentration.

Click on the "Add Constant" box and enter the amount needed to increase the concentration by one unit (the unit that was specified in "Bath Concentration Units" box) in the units specified in the "Units for Add" box.

Concentration Calculation

Example: Concentration Measured In: % by volume

Station size: 50 Gal.

Units for add: Liters

For a 1% change in concentration, the add constant would be:

.01*(50 Gal)*(3.785 Liters/Gal)=1.89 Liters / %. For every 1% change in concentration, an addition of 1.89 Liters must be made. The add constant in this case would be 1.89 (the add amount to change the concentration by one unit).

To test the calculation of the concentration and addition of this component, click the "Test Calculation" button. Note: The "Test Calculation" button will only work if the component screen has been opened from the "Modify Attributes of Selected Component" menu option, if this is a new component then the screen will need to be closed with the "OK" button and reopened to test the calculations. The analysis screen appears.

Enter a number in the "Enter Your Measured Value Here" that simulates the analysis for the component. Compare the value shown in the "Concentration" box with your calculated value using the units to the right of the "Concentration" box. If the numbers are the same, the



"Concentration Constant" is correct. If the numbers are not the same, recheck the calculation of the "Concentration Constant" paying attention to the units specified. Next check the "Delta" value. This value is the difference between the "Target Value" and the calculated concentration. The equation for this is: Delta = [(target concentration) - (measured concentration)].

Now check the number in the "The amount you add is" box and compare the number to your calculated add. If both numbers are the same, the "Add Constant" is correct. If both numbers are not the same, recalculate the "Add Constant" paying attention to the units specified. This equation is used to calculate the addition: Add =(Delta) x (add constant). If the component concentration or add amount cannot be accurately calculated with these formulas, then the complex formula option can be used. See the <u>Complex Formulas</u> section for more information.

Note: Changing the "Target Value" does not affect any of the constants and the add amount will remain correct. Changing units, method of analysis, or station size will cause an error and the affected constant will have to be recalculated.

Process Specification Window



Click in the "Lower Limit" box and enter the number for the lower limit of the process specification for this component. The units associated with this number are the same as those selected in the "Bath Concentration Units" box. The lower limit is used in the component history trending chart and the component SPC screen. Click in the "Target Value" box and enter the target concentration desired after an addition to the station is made. The unit associated with this number is the same as in the "Bath Concentration Units" box. The target value is used in the add calculation after the analysis is entered. Click in the "Upper Limit" box and enter the upper limit of the process specification for this component. The unit for this number is the same as "Bath Concentration Units". The upper limit is used in the component history trending chart and the component SPC screen.

Station Make-up Prompt

To prompt a lab tech with a message, check this box. Clicking on the > or < button as desired. Enter the concentration value in the space provided. Type the desired message in the text box labeled "Instructions".

Station Make-u	p Prompt	
Pri Pri	ompt Lab Technician with the instructions <	0.00
Instructions		Ĵ

Component SPC Setup

Component SPC Setup	Have control chart displa	ay target value after every add
	Display control chart after	er every analysis
I I I	include in Cpk Report	
SPC Rules		
Number of days to ch	eck for SPC	Manually Define Control Chart Parameters Below
chart after each analy	sis	
Flag data point when any single value f	rom analysis	Upper Control Limit 1.750
is above or below the mean by three s	tandard deviations	
Flag data point when 2-out-of-3 consec	cutive points fall	Lower Control Limit U.750
outside two standard deviations below	or above the mean	
Flag data point when 4-out-of-5 consec	utive points all appear	Moving Range Average
below or above one standard deviation	from the mean	
Flag data point when	in-a-row	
on one side of the mean		

The SPC setup options are as follows:

- 1. **Have control chart display target value after every add**: With this option enabled the target value will be plotted whenever an addition is made. This option should be used so that the full range of concentrations are displayed in the trending and SPC charts.
- 2. **Display control chart after every analysis:** Enable this if you want to see a control chart after every analysis. If disabled the control chart will only appear if the analysis is out of control or out of spec.
- 3. **Include in Cpk Report:** Check this to include the component in the Cpk Report.
- 4. **Manually Define Control Chart Parameters Below:** Use this option with care. This option should only be used when the value of the upper control limit, lower control limit, moving range average, and moving range upper control limit are known. The purpose of this setting is to identify drift of a process that is in control.
- 5. Check the rules that you want to be applied to the data for this component in the component control charts. Based on these rules, the control chart will indicate any data points that are out of control. The choice of rules is listed below.

SPC Rules

Enter the number of days of history to include in the SPC calculations. **Note: You should disable the SPC rules until there is enough history to calculate the control limits.** This can be accomplished by un-checking all the rules.



- 1. Flag data point when any single value from analysis is above or below the mean by three standard deviations.
- 2. Flag data point when 2-out-of-3 consecutive points fall outside two standard deviations below or above the mean.
- 3. Flag data point when 4-out-of-5 consecutive points all appear below or above one standard deviation from the mean.
- 4. Flag data point when 7 or 8 (you must choose one) points in-a-row on one side of the mean.

Action Limits



Check this option to enable action limits. Enter the values for the upper and lower action limits. **Note: The value of these limits must be inside the value of the control limits and the spec limits.** Enter the upper and lower limit instructions to be displayed when the respective limit is exceeded. **Note: These instructions are not displayed if any of the control or spec limits are exceeded.**

The "Analysis Procedure" drop-down menu at the bottom of the screen contains other options.

Analysis Procedure

Click this drop-down menu to select the function of text box above the menu.



Analysis Procedures

Click on "Analysis Procedures" in the bottom drop down menu. Click in the text box. Type the analysis procedure in the text box that appears. Click on the "Exit" button. A file is created in the sub-directory of Lab Wizard called procedures. The file name is made as follows: component name-station name-process name.doc.

Add Instructions

Click on "Add Instructions" in the bottom drop down menu. Click in the text box. Type the instructions into the text box that appears. Click on the "Exit" button. The instructions will appear to the right of the component when it is printed out in the add sheet.

Make-up Instructions

Click on "Make-up Instructions" in the bottom drop down menu. Click in the text box. Type the instructions into the text box that appears on the next screen. Click on the "Exit" button. The instructions will appear to the right of the component when it is printed out in the station make-up sheet.

Complex Formulas

Click into the text box and the formula screen will appear. See the <u>Complex Formulas</u> section for details. <u>Formulas must be input from the "Modify Attributes of Selected Component" option.</u>

Click on the "OK" button when done updating the component attributes to save any changes. **Note: Leave all data entries blank if they do not apply.**

By default, the following entries are required if the component has a trigger.

- 1. Trigger value
- 2. Limits (Lower and Upper)
- 3. Target Value
- 4. Concentration constant (This number will not be used when a complex formula is used.)

Note: The setup data is not saved until you exit from setup. It is suggested that you exit setup every 30 minutes to save the setup data.

Setup Menu

The main setup menu resides at the top of the setup screen.

File	Edit	Setup	Preventive Maintenance	Printing	Email	Backup/Restore	Utilities
------	------	-------	------------------------	----------	-------	----------------	-----------

File

- 1 **Cancel:** Exits the setup menu without saving.
- 2 Save and Exit: Saves all modified data and exits the setup menu.

Edit Pareto Causes

This screen allows you to add, remove, and determine how a cause is executed. The pareto cause screen is initiated when any analysis is out of spec (determined by the upper and lower limits). This screen requires the operator to choose a listed cause or add a new cause. This "Out of Spec" cause is then associated with that data.

1. **Include/Exclude Selected Cause from Charts, Paretos, SPC Calculations** button. Highlight the cause to change and click on this button to alternate between include and exclude options. Excluded causes will also not trigger an out-of-spec email to be sent.

2. **Delete Selected Cause** Highlight the cause to be deleted and click on the button.

3. **Add New Cause** Click in the "New Pareto Cause" window and type in the new cause. Click the "Add New Cause" button.

areto Causes	
(Cause is Included on Charts, paretos, and SPC calculations)	Start up
(Cause is Included on Charts, paretos, and SPC calculations)	Analysis too far apart
(Cause is Included on Charts, paretos, and SPC calculations)	Analysis overdue
(Cause is Included on Charts, paretos, and SPC calculations)	Tank level too low
(Cause is Included on Charts, paretos, and SPC calculations)	Tank level too high
(Cause is Included on Charts, paretos, and SPC calculations)	Concentration high due to previous add
(Cause is Included on Charts, paretos, and SPC calculations)	Previous add not made
(Cause is Included on Charts, paretos, and SPC calculations)	POSSIBLE PROBLEM WITH RECTIFIER
(Cause is Included on Charts, paretos, and SPC calculations)	New Bath: Make Up of New Bath is High.
(Cause is Included on Charts, paretos, and SPC calculations)	Due for dump
(Cause is Included on Charts, paretos, and SPC calculations)	New Bath: Make Up of New Bath is Low
(Cause is Included on Charts, paretos, and SPC calculations)	High tempreduce etch time
(Cause is Included on Charts, paretos, and SPC calculations)	BATH OVERFILLED
(Cause is Included on Charts, paretos, and SPC calculations)	entered wrong number
(Cause is Included on Charts, paretos, and SPC calculations)	NEW BATHSp.G. normally low
(Cause is Included on Charts, paretos, and SPC calculations)	Not enough ventalation, PH high
Cause is Included on Charts, paretos, and SPC calculations)	maint.add possibly not made
Cause is Included on Charts, paretos, and SPC calculations)	plated too long
Cause is Included on Charts, paretos, and SPC calculations)	Controller not keeping up with pump.
Cause is Included on Charts, paretos, and SPC calculations)	bath was carbon treated
(Cause is Included on Charts, paretos, and SPC calculations) Circulation in bath keeps stoping.	
Cause is Included on Charts, paretos, and SPC calculations)	Bath needs to be replenished with new solution.
Cause is Included on Charts, paretos, and SPC calculations)	conc.add possibly made
Cause is Included on Charts, paretos, and SPC calculations)	operator overetched
Cause is Included on Charts, paretos, and SPC calculations)	possibly time to change the bath
(Cause is Included on Charts, paretos, and SPC calculations)	bath is being used for rework also
New Pareto Cause	
ADD NEW CAUSE	

Click on the "Close" button to exit this screen.

Global Constants

This screen is used to change the value of existing global constants. You cannot change the name or delete the entry. To change a value, highlight the global constant you want to change. Enter the new value in the control provided then click on the "OK" button. The new value will be used in all formulas that have this global constant.



There are no Global Constants to edit

Global constants are created and used in a

complex formula found under the "modify attributes of selected component option".

If no global constants have been defined you will be presented with the following error message.

For more information about global constants see the **Complex Formulas** section.

User Mode

These screens regulate the protocol used for user log on. Access is allowed (without logging on) to any option that does not require data to be input.

- 1 **Single User Mode:** The user remains logged in until they log out or the software is restarted.
- 2 **Multi-user Mode:** Requires the user to log in every time an option is picked that requires input. After this option is completed, the user is automatically logged out.



Event Triggering Symbols

Use this screen to setup how the preevent and overdue symbols activate. Pre-event symbols that use a time trigger for a station or component can be set to show up any number of minutes before that event is due. Just enter the number of minutes desired in the control. Preevent symbols that use a product throughput trigger for a station or component can be set to show up by any number of product throughput units before the trigger is due.

The setting for the overdue event involves choosing a percent of the appropriate trigger. When the station or component remains due for the entered percentage of the trigger value, the overdue symbol will appear.

Event Not Due ◆ Pre-Event Warning Symbol ✓ Event Due Symbol X Event Overdue Symbol
Settings for Pre-Event Warning Symbol
Time Triggers: Show symbol before an event is due (Minutes).
Product Through-put Triggers: Show symbol before an event is due by this amount.
Settings for Overdue Symbol
Time Triggers: Show overdue symbol after the event has been due for n% of it's trigger value (hrs.).
Product through-put Triggers: Show overdue symbol after the event has been due for n% of its trigger value.
Exit

Example: If the entered value is 10% and the trigger value is 4 hours. The overdue symbol will appear when the event has been due for 0.4 hours. If the product throughput trigger value is 10000 sq. ft. and the entered value is 1%, then the overdue symbol will appear when the event has been due for 100 sq. ft.

Preventative Maintenance

This screen displays the preventive maintenance list. Clicking on an item shows the maintenance recurrence schedule and the next occurrence of the item. Overdue (days) is the number of days, after the pm is due, that it will become overdue if not completed. Both the maintenance recurrence schedule and overdue (days) can be edited from this screen.

	Disable Recurrence	Preventive Maintenance Tasks	
	Change to Classic Style PM Task	Etch Plating Tank	
		Plating Anode Maintenance Resist Strip Cleaner	
	PM Task Name		
	Etch Plating Tank		
	New Style PM Recurrence		
ρļ	Start Date 📮 10/2/2021 9:00:01 AM		
~	Recurrence Pattern Time of Day		
	C Monthly 9:00 AM		
	• Day 1 of every 1 month(s)		
	The First day of every 1 month(s)		
	Next Ocurrence		
	11/1/2021 9:00:00 AM		
	PM Alerting Overdue		
	7 _{days}		
	An 'Overdue' alarm event		
	days after the PM is due.		
	Last Completed	× V	
1	2021-09-15 09:14:36	Consta New DM Tark	
			J
	Link This PM Task With a Process	🐉 Select Link 🛛 Lane 2 - Preplater->Electroless Copper	

If a PM task will no longer need to be completed, but the data for past completions needs to be kept, then selecting the "Disable Recurrence" checkbox will stop Lab Wizard from triggering any future occurrences of the task.

Create New PM Task

Use this screen to add a new preventive maintenance task. Enter the name that will be displayed on the main screen under "PM Task Name" and enter the instructions in the box to the right. Set the date and time for the start of the PM recurrence schedule at the "Start Date."

	PM Instructions			
Task Name				
PM Recurrence				
art Date - 9/15/2021 2:14:56.491 PM EB				
Recurrence Pattern Time of Day				
- Monthly 9.00 AM				
Day 1 of every 1 month(s)				
The First day of every 1 month(s)				
lext Ocurrence				
9/15/2021 2:14:58 PM				
Dist Alexander of				
PM Alerting				
Overdue				
/ days				
will be triggered this many	<			
days after the PM is due.		Create PM and Exit	X Cancel	

Note: The start date will not be the first occurrence of the PM. The start date can be set to a date in the past to target a specific date for the first occurrence. Check the date listed under "Next Occurrence" to insure the date is correct.

The recurrence pattern can be set to weekly, monthly, or yearly. The time of day to issue the PM can also be specified.

Weekly Recurrence Pattern

If the recurrence pattern is set to weekly then the options will be changed to match that pattern. The number of weeks between each occurrence can be set and each day of the week the task should occur on can be selected.

e	Recurrence Pattern	Time of Day
	Weekly	9:00 AM
	Recur every 1 week	c(s) on:
	🗌 Sunday 🛛 🔽 Monday	Tuesday Wednesday
	Thursday Friday	Saturday

Monthly Recurrence Pattern

For a monthly recurrence pattern the task can be scheduled for a specified day number and

recurring a set number of months. If the listed day number is not in one of the months that the task would occur on then it will instead trigger on the closest day number for that month, i.e. if the task is to occur on the 30th of each month then in February the task will occur on the 28th instead. Alternately, the task can be

Recurrence Pattern	Time of Day 9 00 AM
• Day 30 of every 2 m	onth(s)
• The First Tuesday	of every 1 month(s)

scheduled to recur on the first, second, third, or fourth specified day of the week every set number of months.

Yearly Recurrence Pattern

If a yearly recurrence pattern is selected then the number of years between each occurrence can be specified. The task can be scheduled to occur on a specified month and day number. Or the task can be scheduled for the first, second, third, or fourth specified day of the week of a specified month.

Recurrence Vearly	Pattern	Time 9	of Day 00 AN	1
Recur every	1 year(s)			
o On	January	1		
 On the: 	First	day	of	January

The PM task can also be linked to a process, station, or component. Linking the task with a process, station, or component will display the link in the <u>Dashboards</u> if activated. When finished setting up a new PM task, click the "Create PM and Exit" button to return to the manage PM tasks screen.

If the Classic Style of PM tasks is preferred then selecting the "Classic Style" tab will display the window shown below.

Note: The PM description is limited to 75 characters.

PM Description	Note: 75 characters max
	Ŷ
Start Date	Maintenance Interval (days) 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	Save Cancel

Fill in the preventive maintenance description, maintenance interval (days) and overdue (days). Click on the "Save" button to save and return to the preventive maintenance list screen.

PM Instructions

The instructions for a selected component can be changed by clicking the "Edit Instructions for Selected PM" button.

Type the instructions and click the "Save" button to save and return to the PM list screen.



Delete PM Item

Select the PM to delete in the PM list screen. Choose the Delete PM Item menu, a popup window will be displayed to confirm deleting the selected task. Deleting a PM task will also delete all data for that task from the database.

Click the "Exit" button to save all changes and return back to the main process setup screen.

Printing

Add Template

	Print Setup for Add Slips
Fields	Enter what you want to be printed in the box below
Tracking # A	ADD SLIP Tracking #<< <tracking #="">>></tracking>
Time	Date: << <date>>></date>
Process	Time: << <time>>>></time>
Station Add Information	Process: << <process>>></process>
Amount Over Due	Station: << <station>>></station>
Station Add Instructions	Station #: << <station number="">>></station>
	Safety Equipment: Wear Safety glasses, gloves and apron.
	PLEASE MAKE THE FOLLOWING ADDITIONS:
	<< <rdd information="">>></rdd>
	Issued By: << <technician's name="">>> Initials:</technician's>
SETUP PRINT FORMAT	Adds Made By: Date: Time:
HELP	Please return this add slip to the lab.
EXIT	
Number of Copies to Print	

This screen is used to create a customized print template for all add sheets. Clicking on an item in the "Fields" column on the left inserts a variable into the template on the right. When the sheet is printed, the variables are replaced with the appropriate data. On the template, variables are enclosed in brackets like <<<variable>>>.

Example: Clicking on the "Date" field on the left inserts <<<Date>>> into the template on the right at the cursor position and when printed, will be replaced with the actual Month/Day/Year.

Once the add sheet template is filled out, click "Setup Print Format" to preview the results.

Below is a detailed description of each field variable.

- <<<Tracking #>>> This is the tracking number from the main screen which can be included on your printouts. The number increments by one every time an Add slip or a Station Make-up slip is printed. However, it does not increment when you do a test print.
- 2. <<<Date>>> Provides the current date.
- 3. <<<Time>>> Provides the current time of day.
- 4. <<<Station Number>>> Provides the station number.

- 5. <<<Process>>> Name of the process.
- 6. <<<Station>>> Name of the station.
- 7. <<<Add Information>>> List of all components with add amounts along with any instructions to the right of the add amount (if add instructions were created).
- 8. <<<Technician's name>>> Name of the person logged in.
- 9. <<<Amount Over Due>>> Displays the hours or product amount that the event was overdue.
- 10. <<<Spec Parameters>>> Displays the concentration, upper limit, target value, lower limit, and unit for concentration for each component listed.
- 11. <<<Station Add Instructions>>> Add instructions that are included for all components within a station. These add instructions are created in station setup.

Number of Copies to Print: This setting is limited to a maximum of 4. Setting this to zero will not allow any printouts, however, the add is still issued and appears in the "Add and Make-up Issued" control on the main screen.

Setup Print Format

This screen shows how the printout will look. Clicking on the "Test Print" button will print out a sample copy without changing the tracking number. You can change the print font, font size, font color, and font style. To preview add sheets for different processes and stations, use the "Process" and "Station" pull down menus. To leave this screen and return to the "Print Setup for Add Slips" screen, click on the "Exit" button. If any changes have

Type Of Printout	ADD SLIP Tracking #000025
MAKE ADDS TO STATION	Date: 3/11/2019
	Time: 5:04 PM
	Process: Electroless Copper
Font Color	Station: Conditioner 3320
Font Name Times New Size 14	5- 1
	Station #: 2C01
Italic Underline Bold 🛛	Safety Equipment: Wear Safety glasses, gloves and apron.
1	PLEASE MAKE THE FOLLOWING ADDITIONS:
Process	
Electroless Copper	Conditioner 3320 3.9 liters
Station	
Conditioner 3320	
	Issued By: admin Initials:
Test Print	Adds Made By: Date: Time:
	Please return this add slip to the lab.
Exit	

been made to the print format, a "Save Changes to Print Format?" dialog prompt will appear.

To exit the "Print Setup for Add Slips" screen and return to the "Setup" screen, click on the "Exit" button. If any changes have been made, a dialog screen will appear "Save Changes to Print Setup For Add Slips? ".

Make-up Template



This screen is used to setup the printout for the makeup sheets. This screen setup is the same as the "Add Template" screen with the exception the field list. "Makeup Info", the component recipe for making up a new station, replaces "Add Information" and "Station Makeup Instructions" replaces "Station Add Instructions".

Note: For a component to be included in the make-up recipe, the "Unit for New Station Make-up" and "Amount for New Bath Make-up" in the component setup must be filled out. To log the addition to the log file, the "Unit Describing Bath Concentration" of the component setup must be filled out. The order of the components in the recipe can be changed in the "Modify Attributes of Selected Station" selection of Setup.

Out of Spec Template

This screen is for setting up the template for the out of spec sheet. When the out of spec printout option is enabled, a printout is automatically printed using this template.

	Print Setup for Out of Spec Printout
Fields	Enter what you want to be printed in the box below
Tracking # Date Time Process Station Number Spec Parameters Amount Over Due Last Analysis Date OoS Cause and Comments Technician's Name	Dut OF SPEC NOTIFICATION ^ Date:<<
SETUP PRINT FORMAT	
HELP EXIT Number of Copies to Print	
	,

The procedure to make this template is the same as add and make-up templates, only the fields are different. The field choices are Tracking #, Date, Time, Process, Station, Station Number, Spec Parameters, Amount Over Due, Last Analysis Date, OoS Cause and Comments and Technician's Name.

Email

Email Server

Type the address of the SMTP mail server. This is required to enable the email functions. Leave blank if you are not using email. Select the "TLS" switch if this option is needed by the email server. If authentication of outgoing email is required, type in the username and password, otherwise leave blank.

SMTP Mail Server Port
- 25
From Address
From Address
TLS OF
Lisername
Osernanie
Password
Save Cancel

Email Addresses

Type in all email recipients email addresses. Check the days of the week each recipient should receive email.

Use the File>>Save and Exit to save and return to the setup screen.

Ema	Email Addresses Enter email addresses below								
En	mail Address	Email Schedule							
	casey@lab-wizard.com		Sun	Mon	Tue	Wed	Thu	Fri	Sat
En	mail Address	Email Schedule							
	brad@lab-wizard.com		Sun	Mon	Tue	Wed	Thu	Fri	Sat
En	nail Address				Email	Sched	ule		
	support@lab-wizard.com		Sun	Mon	Tue	Wed	Thu	Fri	Sat X
En	mail Address				Email	Sched	ule		
			Sun	Mon	Tue	Wed	Thu	Fri	Sat
En	nail Address				Email	Sched	ule		
			Sun	Mon	Tue	Wed	Thu	Fri	Sat
En	mail Address				Email Schedule				
			Sun	Mon	Tue	Wed	Thu	Fri	Sat
En	mail Address		Email Schedule						
			Sun	Mon	Tue	Wed	Thu	Fri	Sat
En	mail Address		Email Schedule						
			Sun	Mon	Tue	Wed	Thu	Fri	Sat

Email Recipients

Click on an email address to display the assigned alarms for that address. To add an alarm, click on the desired alarm in the "Alarm List", and then click on the "Add" button. The alarm will appear in the "Alarms Assigned to Selected Email Address" list box. To remove an assigned alarm, click on the alarm in the "Alarms Assigned to Selected Email Address" list box, and then click on the alarm in the "Alarm will appear back in the "Alarm List". When any assigned alarm is activated, all recipients that have the alarm assigned are emailed if that day is scheduled for email.

Email Addresses	Alarm List	Alarms Assigned to Selected Email Address
brad@lab-wizard.com casey@lab-wizard.com support@lab-wizard.com	scheduled make up overdue issued add overdue issued make up overdue Issued preventive maintenance overdue concentration out of spec concentration out of control	scheduled analysis overdue
Select the email address to configure the desired alarms	Select an alarm to add to the selected email address	Select an alarm to remove from the selected email address

The assignable alarms are:

- 1. Scheduled analysis overdue
- 2. Scheduled make up overdue
- 3. Issued add overdue
- 4. Issued make up overdue
- 5. Concentration out of spec
- 6. Concentration out of control

Choose File>>Save and Exit menu to save and return to the setup screen.

Test Email

Use this screen to test the email File function. Type the mail server SMTP Server Address Port TLS Use if authentication is required, otherwise leave them blank. address, recipient email address 25 Username (To Address), subject, and From Address message. The "From Address" Password To Address is optional. If password authentication is required for Subject outgoing email, type in the Server Response username and password (leave Message blank if authentication is not required). Activate the "TLS" switch if this option is needed by the email server. Click the "Send" button. The program and server communication is error details code status recorded in the "Server **a** Send source Response" window to aid in ^ troubleshooting. X Cancel

Choose File>>Exit menu to return to the setup screen.

Process Modification

Modifying a Process

To change attributes of a particular process, highlight the process to be modified. Choose "Modify Attributes of Selected Process" from the Process Options pull down menu. The following screen appears.

Make the changes desired and click on the "OK" button.

Deleting a Process

To delete an entire process, choose "Delete Process" from the Process Options pull down menu. Highlight the process in the screen that appears. A prompt appears asking for confirmation.



Electroless Copper Automated Plating	^
Brown Oxide	
Desmear	- 1
Manual Plating	- 1
Nickel/Gold Plate	- 1
Pumice Pre-Clean	- 1
S.E.S. Line 🛌 🔀	- 1
Hot Air Le Are You Sure You Want to Delete Brown Oxide?	- 1
Control de VES Cancel	- 1
	- 1
	*

Modifying a Station

To change attributes of a particular station, highlight the station to be changed. Choose "Modify Attributes of Selected Station" from the Station Options pull down menu. The following screen appears:

Everything on this screen can be edited except the station name. This is also the only place to change the order of the components of a station. The components are printed in the order that they appear in the "Station Makeup Order" window. This applies to both add and makeup slips. When you click on a component in the window, the component goes to the top of the list. Therefore, click on the components in the reverse order that you want them to appear. Grayed out components will not appear on add or make-up slips. The station "Add Instructions" and "Makeup Instructions" are accessed by choosing from the drop down menu. Click into the text box and type the instructions in the screen that appears. These instructions will appear any time a makeup or add sheet is printed (provided the field is in the template). Click "OK" to except the changes or "Cancel" to abort any changes.



Deleting a Station

To delete a station from a process, highlight the process and station. Choose "Delete Station from the Selected Process" from the Station Options drop down menu. The following prompt appears:

You 1% Fro	I have chosen Sulfuric Acid m the Electro	n to delete the station: pless Copper Process.	
	ОК	Cancel	

Click on "OK" to delete or "Cancel" to abort.
Modifying a Component

To make changes to a component, highlight the component. Choose "Modify Attributes of Selected Component" form the Component Options pull down menu. Make the changes desired and be sure to click outside the box of the last entry before clicking on the "OK" button. Failing to do this will nullify the last entry and that change will not take effect.

Note: If a formula is used for the calculation of concentration and add, there must be a formula for both concentration and add. The concentration and add constants will be ignored if a formula is used.

Deleting a Component

To delete a component from a station, highlight the process, station, and component. Choose "Delete Selected Component" from the Component Options pull down menu. The following prompt appears:

 Delete Component	
Sulfuric Acid (PC Grade)	
✓ OK Cancel	

Duplicate/Rearrange

Selecting this option from any of the process, station, or component drop-down menus will bring up the following screen.



The stations and components lists will change based off the selected process and station. The selected process, station, or component can be moved up or down in the list by clicking on the Move Up/Down button in the respective section. Changing the order will change the order the items are listed in on the main screen. Changing the order of the components will also change the order they are listed in on the component analysis screen.

Duplicate Process

When duplicating a process a different name will be required. This will duplicate all stations and components within the process. If the "Reset All Triggers" option is unchecked then the new process will *

Duplicate Station

When duplicating a station the new station can be copied to the same process or another process can be selected with the drop-down menu. If the new station will be in the same process as the original, then the

Duplicate Process
Process to Duplicate Lane 2 - Preplater
New Process Name
Reset All Triggers Z This will reset all of the make-up triggers for each station in the new process along with resetting each component analysis trigger within each station.
Cancel

	Duplicate Station
Station to Duplicate	Etch 1
Copy Station to This Process	Lane 2 - Preplater
New Station Name	2
NOTE: Duplica triggers withir	iting a station will reset the station make-up trigger and all component analysis n the newly created station.
	Done Cancel

name must be different than the original name. All event triggers will be reset for the new station, including all component analysis triggers.

Duplicate Component

When duplicating a component there will be a drop-down menu for both the process and station. If the component is being copied into the same station as the original component, then the new

Duplicate Component
Component to Duplicate Chromic Acid
Copy Component to This Process 💂 Lane 2 - Preplater
Copy Component to This Station 👻 Etch 1
New Component Name
NOTE: Duplicating a component will reset the analysis trigger for the newly created component.
Done Cancel

component will need to have a different name than the original component. The analysis trigger will be reset for the new component.

Complex Formulas

To setup a complex formula, enter the component modification screen and choose

Complex Formula from the drop down menu at the bottom of the screen. Click in the text box above the menu to configure the complex formulas.

Setting Up Complex Formulas for "Sulfuric Acid (PC Grade)"
Concentration Calculation
Ŷ
ADD VARIABLE TO YOUR FORMULA Salid Formula
Add Calculation
ADD VARIABLE TO YOUR FORMULA Valid Formula Enable Conditional Add
Vk Cancel Ok Help

The mathematical functions used are + for addition, - for subtraction, * for multiplication, / for division and ^ for power of x. Parentheses are used to enforce the order of operations.

Note: Variables cannot be typed in the formula box. You must use the "Add Variable to Your Formula" drop down menu to create the variables and insert them into the formula.

Built-in Functions

The following list of functions can also be used in the formulas.

abs(x) absolute value acos(x) arc cosine acosh(x) arc hyperbolic cosine asin(x) arc sine asinh(x) arc hyperbolic sine atan(x) arc tangent atanh(x) arc hyperbolic tangent ceil(x) rounds to next highest integer cos(x) cosine cosh(x) hyperbolic cosine

cot(x) cotangent
csc(x) cosecant
$exp(x)$ exponential e^x
expm1 (e^x)-1
floor(x) rounds to next lowest integer
ln(x) natural log
$\ln p1(x) \ln(x+1)$
log(x) log base 10
log2(x) log base 2
sec(x) secant(x)
sinc(x) sin(x)/x
sin(x) sine
sign(x) if number > 0 returns 1 =0 returns 0 <0 returns -1
sinh(x) hyperbolic sine
sqrt(x) square root
tan(x) tangent
tanh(x) hyperbolic tangent

Note: All angles used in trigonometric functions must be expressed in radians.

Adding Variables

Click the "Add Variable To Your Formula" drop-down menu, the available options are:

- 1. Create New Input
- 2. Create New User Defined Global Constant
- 3. Concentration For
- 4. Add Amount For
- 5. Lower Limit of
- 6. Target Value of
- 7. Upper Limit of
- 8. Concentration Constant for
- 9. Add Constant for
- 10. Amount for Station Makeup for

Inputs fields are used to input numerical values from the analysis screen into the formula. When entering numbers in the analysis screen, the input fields are listed to the right of the control. Enter the number and click on the appropriate field to assign the number to that field, the number will appear in the box to the left of the assigned field. Enter a new number and click on its appropriate field and so on. When all the inputs have been assigned numbers, the formula will be solved and a value will be displayed.

Creating a New Input

Choose this option from the "Add Variable to Your Formula" menu and the following screen appears.



Type the description and unit of measurement and click on the "OK" button. The input field created now appears in the complex formula box. You can now act on this input field by typing in a +, -,*, or /. To use a number in the formula, just type it in.

Note: Once the input has been created, it will now appear at the bottom of the "Add Variable to Your Formula" drop down menu and may be used in other formulas. Example: The following example requires two inputs:

Concentration formula

((<<<INPUT: Absorbance 526 nm>>> *47.88)+(<<<INPUT: Absorbance 603 m>>>*95.34))*.172

Click in the "Concentration Calculation" box on the Complex Formula screen. Into the formula box, type two-left parenthesis "((". Click on the "Add Variable To Your Formula" menu. Choose "Create New Input". In the screen that follows, type "**Absorbance 526"** into the "Input Description" text box. Into the "Unit of Measurement" text box, type "**nm**". Click on the "OK" button. Now type "*** 47.88)**+(" to the right of the input field that was just created.

Click on the "Add Variable To Your Formula" menu. Choose "Create New Input". In the screen that follows, type "**Absorbance 603**" into the Input Description text box. Into the "Unit of Measurement" text box, type "**nm**". Click on the "Ok" button. Now type "***95.34**))*.172". The formula should look identical to the formula above.

Note: When two inputs are used in a concentration calculation, the analysis screen will have all the inputs listed to the right of the numerical input box.

As in a normal analysis, enter your measurement in the "Enter Your Measured Value Here" box, then to the right, click on the appropriate input that was measured. Enter the measurement for the next input and click that input to the right, you will see the measured value to the left of the input name when done correctly. Repeat these steps for all inputs



listed. When all the inputs are satisfied, the formula is solved.

To use a value from another component within the station, choose the appropriate item from the "Add Variable to your Formula" menu. The following screen appears:

Click on the desired component and the "OK" button. The field now appears in the "Complex Formula" box.



Add formula

Example: (<<<Target Value of 3308A>>> -<<<Concentration For 3308A>>>)*5

Click in the "Add Calculation" box on the Complex Formula screen. Type a left parenthesis "(". Click on the "Add Variable To Your Formula" menu and choose "Target Value of". In the next screen, select the component for which the addition is based on (in this example 3308A). Click on the "OK" button and the field appears in the "Add Calculation" box. Type a minus sign "-" to the right of the field that was just created in the formula. Click on the "Add Variable To Your Formula" menu and choose "Concentration for". In the next screen, select the component for which the addition is based on (in this example 3308A). Click on the "OK" button and that field appears in the "Add Calculation" box. Type the following: a right parenthesis, a multiplication sign and the number five ")*5" to the right of the last field.

Conditional Add

This feature is used when an analysis may require an addition that can be either one of two different components determined by its analysis value. To use this feature, click on the check box **Denable Conditional Add** that is located towards the bottom right of the "Add Calculation" formula box. The following screen appears.

Setting Up a Conditional Add for "Conditioner 3320"
Choose Add Component> Conditioner 3320 If Analysis result is > 0.5000
Ĵ
ADD VARIABLE TO YOUR FORMULA Salid Formula
Choose Add Component> Conditioner 3320 If Analysis result is < 0.5000
ADD VARIABLE TO YOUR FORMULA
Ok Cancel

In the upper tan colored box choose the component from the drop down menu that corresponds to the greater or equal than statement for the analysis results. The "If Analysis Result is" value can be changed in the top control only, the bottom control will become the same value. This value, by default, is the target value of the component being analyzed.

Click on the component drop down menu in the bottom box and choose the component that corresponds to the addition that is satisfied by the analysis result indicated. Next enter the add formula that applies to each component in the respective formula box. Click "OK" to save the change, notice the special formula now appears in the "Add Calculation" formula box.

Note: The two components that are used in the conditional add screen must have "None" for an analysis trigger and the "Unit for add" must have an entry.

Creating Global Constants

Global constants are created and used in formulas where a constant may need to be changed over time (titration solution normality or some calibration factor). With the use of global constants, just changing the value of the global constant changes the value in all formulas where it is used.

To create a global constant, click on the "Add Variable To Your Formula" drop down menu. Click on "Create New User Defined Global Constant". The following screen appears.

You are adding a new Global Constant to your formula Please Enter a Global Description, Unit of measurement, and Initial Value
Initial Value for your GLOBAL 1.10000 GLOBAL CONSTANT DESCRIPTION UNIT OF MEASUREMENT
Ok Cancel

Enter the description, unit of measurement, and initial value. Click on the "OK" button. The global constant now appears in the formula. It is also listed at the bottom of the drop down menu "Add Variable To Your Formula" for use in subsequent formulas.

All of the remaining fields that can be used in formulas function very similar to this. For example, to import the concentration of a component into the formula, click on the option "Concentration for" and choose the component from the screen that appears. The field is inserted into the formula at the location where the cursor was.

Note: To edit the value of an existing global constant see the **<u>Global Constants</u>** section.

When using formulas to calculate concentrations and additions, all fields from other components that are used in the formula must be analyzed first. The analysis for a station must remain open until the formula is solved. Closing out the analysis before the formula is solved will cause the values to be lost for the components that have not been analyzed. If you should try to analyze a component that has a field using another component value, and that component has not been analyzed, Lab Wizard will prompt for analysis of that component first.

Test Calculation

After completion of the formulas, click on the *straculation* button and the following screen appears.



Enter a number in the Measured Value control and click on the input field to the right of the control. Verify the concentration and add calculations are correct.

If the formula contains fields from other components, a prompt will appear to enter a pretend value for each field that is in the formula. When all the prompts are completed, enter in the values for any inputs to solve the formula.

Backups

It is important to make regular backups of the Lab Wizard directory in case of hardware failure. The MySQL sub-directory can be omitted for smaller backup sizes. Please contact Lab Wizard support for help restoring from a previous backup. support@lab-wizard.com

Remote Console

The Remote Console is installed on a separate computer from the main Lab Wizard installation. Through the remote console other users are able to view the history and report screens without interrupting technicians entering data. Users that have access level 5 can also make changes in Lab Wizard through the Setup screen from the Remote Console.

Contact sales@lab-wizard.com to enable the Remote Console.

Hardware Requirements

- 1. Operating System: 64-bit Windows 10.
- 2. Video adapter capable of 1920x1200 resolution.

To set the video resolution:

- 1. Right click on the desktop.
- 2. Select 'Display Settings'
- 3. Scroll down to 'resolution' and select 1920x1200 from the drop-down menu.

Installation Instructions

- 1. Ensure the operating system has all updates installed and the system has been restarted.
- 2. Download the latest version of the Remote Console software using the link in your email.
- 3. Once the download is complete, right-click on the RemoteConsoleInstaller.zip file and select 'Extract All' then click the 'Extract' button.
- 4. Close any open programs and windows.
- 5. Double-click the setup.exe file and follow the prompts.
- 6. Proceed through the installation using all of the default options, once the entire installation is complete you will be prompted to restart, DO NOT exit before this.
- 7. You must have administrator privileges in order to install the software, when you are prompted enter the administrative credentials.
- 8. This software requires a license file, which is generated by the Lab Wizard team. The remote console will need to connect with the computer that has the main Lab Wizard installation to access the license file and database.

Updating the Remote Console

Any time the remote console is launched a small window will appear asking to check for updates. Selecting 'No' will simply launch the

Check for u	pdates?	
Yes	No	

remote console. Selecting 'Yes' will check for any updates, if an update is found then it will be automatically downloaded and installed before launching the remote console.

To check the current version of the remote console, Select 'Version' under the 'Help' menu on the main screen.

Current running version is 11.4.47
ОК

Remote Console Setup

On the main Lab Wizard computer

Before launching the remote console, the remote console will need to be enabled from the main Lab Wizard setup screen. In the process setup screen under the Utilities menu option is the Remote Config.

The name displayed in the "Host Name" box will depend on the name of the computer Lab Wizard is installed on, this name will need to be entered on the remote console to establish the connection.

Click the "Enable Remote" button to allow a remote console to connect to this installation of Lab Wizard. Lab Wizard will make changes to network connections to allow the remote console to connect to this device, this will require administrative access.

Host Name	
DESKTOP-LP1P7ER	
Enter this host name on the remote console client machines.	
Check Configuration Enable Remote Science Exit	

1. Open j 2. Create 3. Share t	oorts 3306 inbound and outbound in the Firewall a user in the database to use for remote connections the Lab Wizard folder for the remote console to connect
	Yes No
_	
k	Remote User: Enabled
te	Outbound Firewall Rule: Enabled Outbound Firewall Rule: Enabled Lab Wizard Folder Share: Enabled
	OK

Do you want Lab Wizard to enable the remote console?

This will attempt to:

After enabling the remote console click the "Check Configuration" button to verify that the appropriate ports are open and the Lab Wizard folder is being shared.

To disable the remote console click the "Disable Remote" button. This will also require administrative access to close the open ports and stop sharing the Lab Wizard folder.

On the remote console computer

The first time the remote console is opened it will bring up the remote connection setup screen.

Enter the name of the computer that was displayed on the configuration window from the main Lab Wizard computer in the space for the host name.

Manage Remote Sessions		×
	Remote Connection Setup	
Lab Wizard Host Name	(The host name can be obtained from the main Lab Wizard computer Lab Wizard -> Setup -> Utilities)	
Database Name	(The default database name is LW, under normal circumstances this will not change)	
LW		
Lab Wizard folder path	(This is the network path to the Lab Wizard folder on the host computer)	
ക		
Test Connection	Br)wse

The database name will be listed as "LW" by default, this is likely correct unless the name was changed when first installing Lab Wizard.

Click on the "Browse" button to the right of the "Lab Wizard folder path" box to bring up a file browser window, use this window to navigate to the Lab Wizard installation folder on the host computer.

Once all of the connection options are filled, click on the "Test Connection" button to confirm the connection options are correct. A window will appear to confirm the company name and location as displayed at the bottom of the main Lab Wizard screen. Once the connection has been confirmed the "Save Connection" button will no longer be grayed out. Clicking this button will prompt to enter a name for the connection, this can be any name to identify this connection.

Exiting the connection setup screen with a valid connection will bring up the <u>Operator Log In</u> screen, this will be the same log in information as for the Lab Wizard installation the remote console is connected to.

Saved connections can be deleted from this window with the "Delete a Saved Connection" button.

Remote Console Main Screen

The main screen will show the active connection. If multiple connections are saved then the connections can be changed with the drop-down menu on this screen, click on the "Reinitialize" button to connect to the newly selected connection.

To log in as a different operator, click on the "Re-initialize" button to bring up the operator log in screen again.

Lab Wizard Remote Console	×
Help	
Lab Wizard Remote Console	
Active Connection	
Main	
History Reports V Re-Initialize	
Dashboards	

The "Set up Connections" button will bring up the connection setup screen again to add saved connections or make changes to a previously saved connection.

If the Dashboards are enabled then the 'Dashboards' button will appear at the bottom of the window. See the <u>Dashboards</u> section for more information.

History drop-down

The history drop-down menu allows access to the same history screens as in the main Lab Wizard installation. The options in this menu are:

<u>Process History</u> <u>Station History</u> <u>Component History</u> <u>Preventive Maintenance History</u> <u>Advanced History</u>

Reports drop-down

The reports drop-down menu allows access to the same report screens as in the main Lab Wizard installation. The options in this menu are:

<u>Events Status Report</u> <u>Out of Spec Report</u> <u>Cpk Report</u> <u>Preventive Maintenance Report</u> <u>Station History Report</u>

Tank Setup

If a log in with access level 5 is used, then the "Tank Setup" button will appear to the right of the reports dropdown menu. This button gives access to the setup screen, see the Lab Wizard Setup section for more information. Caution should be used when making changes from the remote console! If changes are made while a



technician is entering data then there may be unexpected results.

If another user is accessing the setup screen, then a pop up will appear asking to disconnect the other user and will state which user is accessing the setup screen. Another window will appear to confirm disconnecting the other user.

The same window will also appear in the main Lab Wizard

setup screen if another user is connected through the Remote Console.

It looks like a remote se currently accessing the	ssion for adm setup and has	in is
been for 1 minute.		
Do you want to disconnect remote admin?		
Yes	No	

Dashboards

The Dashboards can be run from any computer that has the Remote Console installed to allow for a faster checkup on statuses or SPC data from Lab Wizard. Contact <u>sales@lab-wizard.com</u> to enable Dashboards.

SPC Component Dashboard

The SPC Component Dashboards displays a number of component graphs to easily track the concentrations and insure the components are kept within the spec ranges.



Each dashboard can have multiple pages that it cycles through and will regularly check the Lab Wizard database for updates in the data. A timer for when the page will change is displayed in the top right corner. The frequency of data updates and page changes can be set for each dashboard in the setup screens explained below.

Live Status Dashboards

The Live Status Dashboards displays the event triggers for the processes, stations, or components set to that dashboard. This allows a quick visualization of what analysis, make-ups, or issued adds are due or overdue.

& Lab Wizard	Live Status Viewer		Cuposit		Refresh Timer 23 🗳 Exit
Station	Analysis	Add Slips	Corrective Action	Other Item	Details
Cuposit->Promoter	10 Days late				Circuposit Promoter 3308A analysis 10 Days late
Cuposit->Neutralizer					
Cuposit->Hole Prep					
Cuposit->Conditioner					
Cuposit->G-5 Microetch					
Cuposit->Catalyst Predip					
Cuposit->Catalyst	12 Days late				Cataposit 44 analysis 12 Days late
Cuposit->Electroless Copper	24 Mins due				Cuposit Z analysis 24 Mins due
Cuposit->Sulfuric Acid		17 Mins late			Sulfuric Acid 93% add 17 Mins late

Preventative Maintenance items that have been linked to a process, station, or component will be displayed in the 'Other Item' column. See the <u>Preventative Maintenance</u> section for more information.

A timer for the next update in status times is displayed in the top right corner. The update time can be changed from the setup screen explained below.

Dashboards Setup

The first time the Dashboards are accessed either from the 'Dashboards' button on the Remote Console or from the 'Setup' menu on the main Lab

No dasboards were detected, are you set	ting up a dashboard for the first time?
Yes	No

Wizard screen a pop-up window will indicate that no dashboards were found.

Click 'Yes' to close this window and click on the 'Manage Dashboards' button at the bottom of the main Dashboards screen. **Note: The 'Manage Dashboards' screen requires access level 4 or 5.**

Dashboard Typ Live Status Das	e shboard		Display Selected	Dashboard
Live Status Das	shboard		Display Selected	Dashboard
	Manage Dashboard	S	Exit	v

The 'Display Selected Dashboard' button will be grayed out if there is no dashboard selected.

Manage Dashboards Screen

The below screen will appear when the 'Manage Dashboards' button is clicked.



When first setting up a Component SPC Dashboard, begin by clicking on the 'Manage SPC Pages' button.

To switch to managing Live Status Dashboards, select the 'Live Status Dashboard' tab at the top of the window to show the following screen.

Component SPC Dashbo	omponent SPC Dashboard Live Status Dashboard				
Lab Wiz	Lab Wizard Live Status Dashboard Management				
Process	Analysis	Add Slips	Corrective Action	Other Item	Details
_					
			Exit		

Click on the 'Manage Live Status Dashboards' to begin setting up a Live Status Dashboard.

Component SPC Page Setup

To begin setting up a Component SPC Dashboard click the 'Manage SPC Pages' button on the Manage Dashboards screen.

SPC Page Manager			Save Changes Exit
Page List	Page Parameters	Page Name test page	Data Slots 2 SPC
A A A A A A A A A A A A A A A A A A A		Data Slot 1	r Strike->Copper Sulfate
New Page Delete Selected Page		Data Slot 2	er Strike->Sulfuric Acid

Clicking on the 'New Page' button will display a window for selecting the page parameters for a new page, the 'Add Page' button will add this page to the Page List on the left of the screen.

		Page Para	ameters	
	Page Name			
	Data Sl	ots		
	2 SPC			
-				
	<u>~</u>	Add Page	■ Cancel	

The number of Data Slots can be changed with the drop-down menu, the options are two, four, or six component SPC graphs.

These parameters can be changed for the selected page on the SPC Page Manager screen.

For each data slot the component can be selected with the 'Select Component' button, this will display a pop-up for navigating through the Processes and Stations to select the desired component. The line color can be changed by clicking on the colored square, a small window will appear for selecting any color, brighter colors are recommended on the black background. And the line width can be set to 1-5 with the drop-down menu with 1 being the thinnest line and 5 being the widest.

The selected page can be deleted with the 'Delete Selected Page' button.

Be sure to click the 'Save Changes' button before exiting this window or selecting a different page.

Component SPC Dashboards Setup

Click on the 'Manage SPC Dashboards' button from the Manage Dashboards screen to display the following window.

SPC Dashboard Manager	👍 New SPC Dashboard 💽 Save 📃 💻 Dele	ete Dashboard 💽 Help 🛛 🖾 Exit
SPC Dashboard Manager	▶ New SPC Dashboard ▲ Save ■ Dele SPC Dashboard Parameters SPC Dashboard Parameters Mutlibond Page Cycle Time 30 Seconds SPC Time Window 30 Days Refresh Data Every 30 Minutes Update Parameters 	te Dashboard Page Order for the Selected Dashboard Page Order for the Selected Dashboard Multibond Acid Cleaner Multibond 100 Rearrange Pages More Up More Up More Down Add Page to Dashboard Remove Selected Page Manage Pages Components In This Page
		Multibond->MB PreDip->MB 1008 Multibond->MB PreDip->M-Prox 50

Click on the 'New SPC Dashboard' button to display the SPC Dashboard Parameters window.

The 'Page Cycle Time' is the length of time each page is displayed for this dashboard.

The 'SPC Time Window' is the number of days that will be displayed in each graph.

The dashboard will check for new data according to the 'Refresh Data Every' cell Setting the refresh time too frequent can slow down the system.

Dashboard Parameters

 Dashboard Name

 cycleTime
 30

 Seconds

 spcTime
 30

 Days

 refresh
 30

 Minutes

These parameters can all be changed after creating the dashboard as well, be sure to click the 'Update Parameters' button if any changes are made.

The right side of the screen shows the pages that will be displayed for this dashboard. Use the 'Add Page to Dashboard' button to add a page to the list. The 'Manage SPC Pages' screen can be accessed from here with the 'Manage Pages' button.

The pages will be displayed in the dashboard according to the order they are listed on this screen. Use the 'Move Up' and 'Move Down' buttons to reorder the pages.

The components that are tracked for the selected page will be displayed in the box at the bottom of this section.

Multibond Acid Cleaner		*	
Multibond Predip			
Multibond 100		Real (Move Up
Add Page to Dashboard	Remove Selected Page	Manage Pages	
Components in This Page	MD 100D		
Multibond->MB PreDip->	MB TOOB		
Multipoliti->MB PleDip->	MI-PTOX 50		

Be sure to click the 'Save' button before exiting this screen or changing the selected dashboard.

Live Status Dashboard Setup

Clicking on the 'Manage Live Status Dashboards' button on the 'Live Dashboards Management' tab will display the following screen.

	Lab Wizard Live Status Dashboard Setup			
Status Dashboards		Dashboard Column Names		
Resist Strip	Process	Analysis Add Slips Corrective Action Other Item Details Processes in this dashboard:		
	Dashboard Name Lane 2 Dashboard Level Processes Data Refresh (min) 1	List Management> Lane 2 - Preplater Lane 2 - Rack Strip		
	Create New Status Dashboard Delets Selected Dashboard Save Dashboard Help	Move Up Move Down		
	Melp E Exit			

The available Status Dashboards will be listed on the left of the screen.

The 'Create New Status Dashboard' button will display a window for naming the new dashboard.

Status Dashboard Name				
	OK OK	Cancel		
		Cuncer		

The dashboard level can be changed with the drop-down menu below the Dashboard Name. Changing the level will clear all of the processes, stations, or components for the current dashboard. The displayed columns names will also change to reflect the selected dashboard level.

Dashboard Column Names					
Station	Analysis	Add Slips	Corrective Action	Other Item	Details
Dashboard Column Names					
Component	Result	Add Slips	Corrective Action	Other Item	Details

The selected dashboard can be deleted with the 'Delete Selected Dashboard' button.

Be sure to click the 'Save Dashboard' button before exiting the screen or selecting another dashboard.

How frequently the dashboard checks for status updates can be changed with the 'Data Refresh' box. Setting the refresh time too low can slow down the system.

4

1

To add an item to the dashboard click the 'Add New' button, a popup will appear to select the process, station, or component according to the level of the current dashboard. The new item will be added to the bottom of the list.

	Processes in this dathboard:
	Flocesses in this dashboard.
	Lane 2 - Preplater
Management>	Lane 2 - Rack Strip
Add New	
Remove Selected	
Move Up	
Move Down	

The order of the list will determine the

order of the rows as they appear on dashboard, use the 'Move Up' and 'Move Down' buttons to rearrange the list.

An unwanted item can be deleted by selecting it and clicking the 'Remove Selected' button.